

# Imray Correction Notice

08 December 2011

## Chart C64 WGS 84

*Edition May 2004*

*Date of printing Aug 2007*

The following corrections should be noted:

### 1 Lough Foyle, Greencastle (Plan D)

Mariners are advised that, as of November 2007, works are in progress to construct a new breakwater at Greencastle Harbour and should therefore take extra care caution in the harbour area. (ILNW 27/07)

### 2 Belfast Docks (Plan G)

Delete chimney syms and associated lgds in 54°37'·05N 5°54'·40W and 54°37'·54N 5°54'·05W. (ILNW 115/08)

### 3 Islay, Rubha a'Mhàil (*Correction superseded - see ILNW 314/08*)

From April 2008, the lighthouse in position 55°56'·18N 6°07'·41W will be subject to engineering works. These works are expected to be completed by August 2008. During this period, the range will be reduced from 24/21M to 12/10M (ILNW 186/08)

### 4 Islay, Bowmore

Insert Lt FI.G.3s2M in 55°45'·56N 6°17'·32W (ILNW 296/08)

### 5 Islay, Rubha 'a' Mhàil

From July 2008, the existing sectored temporary Lt in 55°56'·18N 6°07'·41W has been withdrawn and replaced with an unsectored temporary Lt FI(3)15s47m12M. A permanent Lt is expected to be re-established in late summer 2008. (ILNW 314/08)

### 6 Lough Foyle (Plan D) (*Correction superseded - see ILNW 528/08*)

Insert R can Lt buoy **Rinenore** Oc.R.5s in 55°06'·10N 7°12'·41W (ILNW 331/08)

### 7 Lough Foyle, Greencastle (Plan D)

Amend Lt FI(2)WRG.3s4m11-9M to FI.G.3s5M in 55°12'·10N 6°59'·10W.

Insert Lt FI.R.3s5M in 55°12'·11N 6°59'·19W (ILNW 387/08)

### 8 Lough Foyle, Approaches to Londonderry (Plan D)

Substitute R Lt bn with rectangular topmk:

**McKinney's** FI.R for R can Lt buoy **McKinney's** FI.R.5s in 55°11'·28N 7°00'·05W.

**Salt pans** FI.R for R can Lt buoy **Salt pans** FI.R.2·5s in 55°10'·52N 7°03'·11W.

**Clare** Q.R for R can Lt buoy **Clare** Q.R in 55°09'·94N 7°05'·04W.

**Rinenore** Oc.R for R can Lt buoy **Rinenore** Oc.R.5s in 55°06'·10N 7°12'·38W.

Substitute G Lt bn with triangular topmk:

**Castlecary** FI.G for G con Lt buoy **Castlecary** FI.G.4s in 55°10'·06N 7°05'·24W (ILNW 528/08)

### 9 Islay, Rubh'an Duin

An additional red sector has been added to Lt FI(2)WR.7s15m11/8M in 55°44'·69N 6°22'·34W, so that the sectors are now as follows: **197°-R-218°-W-249°-R-350°-W-036°**. (ILNW 594/08)

### 10 Islay, Rubh'a Mhàil

Substitute Lt FI(3)15s45m19M for FI(3)WR.15s24/21M in 55°56'·18N 6°07'·41W and delete assoc Lt sectors. (ILNW 595/08)

### 11 Larne Lough (Plan F)

Insert Y spher Lt buoy with x topmk FI.Y.5s in 54°49'·90N 5°46'·48W (ILNW 18/09)

### 12 Bangor Bay (Plan I)

Amend range of Lt Iso.R.12s14M to 9M in 54°40'·03N 5°40'·33W (ILNW 154/09)

### 13 West Loch Tarbert (Main Chart & Plan B)

Uncharted rocks have been reported within West Loch Tarbert. Mariners are therefore advised to proceed with caution when navigating within the confines of the loch. (ILNW 354/09)

**14 Sound of Islay, Port Askaig**

Insert Lt Q.R in 55°50'·93N 6°06'·27W (ILNW 427/09)

**15 Belfast Lough (Plan G)**

Insert 0·8m Wk in 54°40'·34N 5°47'·18W (ILNW 470/09)

**16 Crinan Canal**

The Crinan Canal will be closed for transit from 14th December 2009 until 15 March 2010 due to essential engineering works. For further details contact the Crinan Canal Office. (ILNW 4/10)

**17 Sanda I. eastwards**

Insert A/S at R can Fl(3)R.18s Lt buoy in 55°16'·91N 5°32'·48W (ILNW 146/10)

**18 Lough Foyle, Greencastle (Plan D)**

Insert E card Lt bn VQ(3)5s in 55°11'·98N 6°59'·31W.

Add breakwater joining Lt bn to shore at 55°12'·04N 6°59'·41W (ILNW 172/10)

**19 Bangor Bay (Plan I)**

Delete Lt Dir.Oc.WRG.10s in 54°39'·98N 5°40'·15W (ILNW 227/10)

**20 Ireland, Larne northeastwards, Hunter Rk**

Insert A/S at S Hunter Rk Lt buoy in 54°52'·69N 5°45'·30W (ILNW 350/10)

**21 Belfast Lough**

Amend Lt LFI.10s to Iso.4s at Fairway Lt buoy, plus delete Horn, in 54°41'·71N 5°46'·24W (ILNW 351/10)

**22 Larne northeastwards, East Maiden**

Amend Lt Fl(3)20s29m24M to Fl(3)15s29m23M in 54°55'·75N 5°43'·67W. Auxiliary Lt and Racon remain unchanged. (ILNW 386/10)

**23 Belfast Lough (Plan G)**

Substitute Wk depth 4·7m for Wk depth 0·8m in 54°40'·34N 5°47'·18W (ILNW 432/10)

**24 Belfast Lough (Main chart & Plan G)**

Substitute:

Wk depth 7·8m for non-dangerous wk in 54°45'·95N 5°40'·76W

Wk depth 9·1m for non-dangerous wk in 54°41'·87N 5°40'·36W (ILNW 456/10)

**25 Larne, Chaine Tower (Main chart & Plan F)**

Amend range of Lt to 16/12M in 54°51'·27N 5°47'·88W (ILNW 498/10)

**26 Sound of Jura, Approaches to Craighouse**

Substitute Lt bn Fl.R.6s3m5M for bn in 55°49'·98N 5°56'·43W (ILNW 120/11)

**27 Port Ellen (Plan C)**

Works are currently in progress to reconstruct the pier at Port Ellen. Mariners are advised to navigate with caution in harbour waters. (ILNW 147/11)

**28 The Skerries northeastwards**

Insert R can Lt buoy Fl.R.5s with assoc. A/S in 55°13'·90N 6°36'·90W (ILNW 347/11)

**29 Larne Lough**

Amend Lt to Fl.12M in 54°49'·59N 5°47'·81W (ILNW 458/11)

*Edition May 2004*

*Date of printing May 2004*

The following corrections should be noted:

**1 Amend note 'Local Magnetic Anomaly'** to read 'Abnormal magnetic variation of as much as  $\pm 4\cdot 5^\circ$  from the normal . . .' (ILNW 160/04)

**2 Belfast Lough (Plan G) Latitude Scale**

The latitude scale has been incorrectly numbered and should read 37', 38', 39', (54°40'N is correct) 41', 42', 43', 44', 45' and 46'. (ILNW 273/04)

**3 Port Ellen (Plan C)**

Insert Lt Fl.R.5s3M at R Bn with topmk in 55°37'·61N 6°11'·6W (ILNW 25/05)

**4 North Channel, Larne apps**

Delete Whis at **S Hunter Rock** Lt buoy in 54°52'·7N 5°45'·3W (ILNW 151/05)

**5 Sound of Islay, Carragh an t'Sruith**

Amend Lt to Fl.3s8m9M in 55°52'·32N 6°05'·76W (See correction No.6) (ILNW 289/05)

**6 Sound of Islay, Carragh an t'Sruith**

Delete white sector of Lt in 55°52'·32N 6°05'·76W (ILNW 346/05)

**7 Mull of Kintyre**

Delete Horn Mo(N)90s in 55°18'·0N 5°47'·9W (ILNW 381/05)

**8 Sound of Islay, McArthur's Head**

Amend range of Lt to 13/10M in 55°45'·8N 6°02'·9W (ILNW 419/05)

**9 Islay, Rubh and Duin**

Amend Lt to Fl(2)WR.7s15m11/8M in 55°44'·7N 6°22'·3W (ILNW 7/06)

**10 Larne, Curran Point (Plan F)**

Move Bns with topmks: red to 54°50'·27N 5°48'·01W and green to 54°50'·43N 5°47'·92W (ILNW 60/06)

**11 Rathlin Island**

Substitute depth 8·6m for 0·8m at Wk in 55°17'·13N 6°12'·62W (ILNW 165/06)

**12 Larne (Plan F)**

Delete Horn(1)30s at Barr's Pt in 54°51'·5N 5°46'·8W (ILNW 242/06)

**13 Sound of Jura, Bow of Knap**

Insert W card Lt buoy Q(9)15s in 55°53'·05N 5°41'·97W (ILNW 342/06)

**14 Lough Foyle (Chart & Plan D)**

Delete Whis at **Lough Foyle** Lt buoy in 55°15'·3N 6°52'·6W (ILNW 364/06)

**15 Sound of Jura, Bow of Knap**

Delete Iso danger Bn in 55°53'·07N 5°41'·69W (ILNW 371/06)

**16 N Ireland, Larne Apps**

Amend Lt on **N Hunter Rk** Lt buoy to Q in 54°53'·05N 5°45'·12W (ILNW 388/06)

**17 Portrush north-north westwards**

Insert spec pillar Lt buoy Fl.Y.5s in 55°18'·13N 6°44'·89W (ILNW 466/06)

**18 Portrush westward**

Insert sym & lgd *Diffuser* in 55°12'·33N 6°42'·10 W and spec pillar Lt buoy with topmark Fl(2)Y.10s close NW. Insert outfall pipeline from diffuser to 55°11'·75N 6°41'·29 W (shore). (ILNW 17/07)

**19 Dunagree Point (Chart & Plan D)**

Delete fog sig Horn(2)30s at Dunagree Pt Lt in 55°13'·6N 6°55'·9W (ILNW 151/07)

**20 Lough Foyle (Plan D)**

Amend **Glenburnie** Lt in 55°10'·42N 7°01'·60W to Oc.R.6s3m3M and **Claddagh** Lt in 55°05'·04N 7°13'·38W to Oc.G.6s4m3M (ILNW 204/07)

**21 Colonsay, Scalasaig**

Amend Lt Ldg2F.R.(occas) in 56°04'·1N 6°11'·0W to Ldg2Iso.G. (ILNW 289/07)

**22 Belfast Lough, Grey Pt south-westwards (Plan G)**

Delete bn in 54°40'·25N 5°46'·05W. Add: Y bn with diamond topmk in 54°40'·13N 5°46'·00W; sym and lgd *Obstn* and spec con Lt buoy Fl(2)Y in 54°40'·41N 5°45'·93W; and outfall pipe from 54°40'·14N 5°46'·00W (shore) to *Obstn* sym. (ILNW 294/07)

**23 Belfast Lough, Carrickfergus south-eastwards (Plan G)**

Delete anchorage in 54°42'·2N 5°47'·6W (ILNW 294/07)