

Imray Correction Notice

18 September 2018

ICD13

Chart D13 Undetermined Datum

Edition 2007

Versions available:

New Edition (Corrected to June 2007)

NOTE Below is a complete list of corrections issued since the 2007 edition of this chart was published. Corrections are listed chronologically in ascending order.

1 Cabo Codera (*Correction amended - see ILNW 376/11*)

Amend Lt to Fl.6s551ft13M in 10°34'·1N 66°03'·2W (ILNW 484/08)

2 Isla de Margarita westwards, Bajo Ostial

Insert W card pillar Lt buoy Q(9)10s in 11°03'·1N 64°28'·8W.

Delete Lt VQ(9)10s4M close by. (ILNW 37/09)

3 Isla Cubagua, Pta Brasil (*Correction amended - see ILNW 492/13*)

Amend radar beacon at Lt from Racon(G) to Racon(M) in 10°49'·9N 64°12'·6W (ILNW 91/09)

4 Islas Piritu northwards

Insert depth 3·5fm enclosed by dangerline in 10°25'·1N 65°00'·4W, plus assoc. lgd Rep (2009). (ILNW 449/09)

5 Cumana (Plan A)

Cumana marina, which in the past had a good reputation, is reportedly in a rundown condition. (ILNW 87/10)

6 General Notice

Before visiting this area, mariners are advised to check www.safetyandsecuritynet.com.

The Venezuelan HO changes light characteristics on a regular basis, making it difficult to keep corrections up to date. Lights are seldom moved, but characteristics are regularly changed. (ILNW 138/10)

7 Cabo Codera

Amend Lt Fl.6s551ft13M to Fl.2·5s551ft13M in 10°34'·2N 66°03'·2W (ILNW 376/11)

8 Farallon Centinela

Amend Lt Fl.12s145ft19M to Fl.12s124ft25M in 10°48'·9N 66°05'·6W (ILNW 377/11)

9 Isla de Margarita, Morro de Robledal

Amend Lt Fl.10s262ft11M to Fl.7·5s262ft19M in 11°02'·60N 64°22'·96W (ILNW 25/12)

10 Higuerote

Delete Lt Fl.R in 10°29'·2N 66°06'·0W (ILNW 199/12)

11 Isla La Tortuga northeastwards

Insert Y superbuoy Fl.Y.4s in 11°00'·25N 65°07'·10W (ILNW 293/12)

12 I. Morro Pelotas

Delete Lt Fl(2)12s250ft15M in 10°18'·29N 64°41'·07W (ILNW 392/13)

13 Bahía de Barcelona

Delete Lt IQ.Y in 10°06'·4N 64°53'·5W (ILNW 443/13)

14 Isla Cubagua, Pta Brasil

Amend radar bn at Lt Racon(M) to Racon(G) in 10°49'·9N 64°12'·6W (ILNW 492/13)

15 Cumana (Plan A)

Insert:

drying wk in 10°27'·65N 64°11'·74W

dangerous wk in 10°27'·45N 64°11'·69W (ILNW 54/14)

16 Bahía de Pozuelos

Insert drying wk in 10°13'·30N 64°40'·00W (ILNW 55/14)

17 Cumana westwards

Insert lit platform in 10°26'·45N 64°13'·97W (ILNW 87/14)

18 Bahía de Barcelona

Insert RW safewater pillar Lt buoy Fl.10s in 10°10'·6N 64°49'·0W (ILNW 422/15)

19 Isla de Margarita W, Morro del Robledal

Insert Lt Fl.8s269ft18M in 11°02'·60N 64°22'·63W. (*Correction superseded – see ILNW 497/16*)

Delete Lt Fl.7·5s262ft19M close W. (ILNW 54/16)

20 Bahía de Pozuelos

Amend range of Los Borrachitos Lt to 6M in 10°15'·1N 64°45'·7W (ILNW 65/16)

21 Bahía de Barcelona

Amend RW Lt buoy to Iso.10s in:

10°08'·9N 64°51'·6W

10°07'·5N 64°50'·8W (ILNW 242/16)

22 Carenero (Main chart & Plan C)

Amend range of Lt to 12M in 10°31'·9N 66°07'·3W (ILNW 245/16)

23 Isla de Margarita W

Delete Lt Fl.8s269ft18M in 11°02'·6N 64°22'·6W (ILNW 497/16)

24 Cumana W

Delete:

Lit platform in 10°26'·45N 64°13'·97W

YBY West pillar Lt buoy Q(9)15s in 10°27'·14N 64°12'·24W (ILNW 505/16)

25 Isla de Margarita NW

Delete Igd *Shoaling Reptd (1961)* centred on 11°04'·5N 64°28'·5W (ILNW 51/17)

26 Bahía de Pozuelos

Amend R pillar Lt buoy Fl.R to Fl(2)8s in 10°14'·87N 64°38'·95W (ILNW 143/17)

27 Bahía de Barcelona

Insert superbuoy sym. in 10°09'·32N 64°51'·40W. This buoy marks the seaward end of a new submarine pipeline. Yachtsmen are advised to navigate with caution in the vicinity. (ILNW 144/17)

28 Isla de Margarita W

Insert Lt Fl.8s269ft18M in 11°02'·5N 64°22'·6W (ILNW 339/18)

29 NOTICE TO MARINERS

This chart is no longer supported with notice to mariner corrections. No future notice to mariner corrections will be issued against this chart. (ILNW 465/18)