Imray Correction Notice ICE1-4

4 October 2023

Chart E1 wgs 84

Edition 2021

Versions available:

New Edition (corrected to October 2021) Update (corrected to October 2022) Update (corrected to October 2023)

NOTES

Below is a complete list of corrections issued since the 2021 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction. Any further corrections will be applicable from that point onwards.

1 São Miguel, Ponta do Arnel

Amend Lt FI(2)10s65m19M to LFI(2)10s65m19M in 37°49'.5N 25°08'.2W (ILNW 615/21)

2 Lajes das Flores (Plan A)

Insert R port hand pillar Lt buoy **Lajes** FI(2)R.12s in 39°22'·80N 31°09'·87W. Delete Lt FI(2)R.12s9m9M close SW (ILNW 281/22)

3 Northern Breakwater (Plan B) (correction superseded see ILNW 24/23)

Amend range of Lt Fl.G.3s12m9M to 2M in 38°32'·26N 28°37'·32W (ILNW 289/22)

4 Lajes do Pico (Plan C)

Insert Y spher Lt buoy ODAS FI(5)Y.20s in 38°23'.97N 28°15'.72W (ILNW 381/22)

5 Approaches to Angra do Heroísmo (Plan G)

Work is underway to extend the pier at Porto Pipas. Insert lgd *Works in progress (buoyed)* centred on 38°38'·96N 27° 12'·95W

Insert Lt FI.Y.6s2M in 38°38'.99N 27°12'.93W (ILNW 3/23)

6 Northern Breakwater (Plan B)

Amend range of Lt Fl.G.3s12m2M to 9M in 38°32'·26N 28°37'·32W (ILNW 24/23)

7 Ponta da Ilha, Pico

Amend Lt FI(3)15s28m24M to FI(2)20s28m20M in 38°24'·8N 28°01'·9W (ILNW 123/23)

8 Cais do Pico, Pico

Replace Lt Oc.R.6s10m6M with Lt Fl.G.3s12m12M in 38°31'·9N 28°19'·2W (ILNW 255/23)

9 Vila do Porto (Plan J)

Insert Lt Fl.R.3s6·5m3M in 36°56'·63N 25°08'·97W (ILNW 256/23)