

# Imray Correction Notice ICB2-2

27 October 2020

## **Chart B2** WGS 84 *Edition 2018*

*Versions available:*

*New Edition (corrected to May 2018)*

*Update (corrected to May 2019)*

*Update (corrected to October 2020)*

### **NOTES**

*Below is a complete list of corrections issued since the 2018 edition of this chart was published.*

*Each correction is issued with an ILNW reference number and year.*

*Corrections are listed chronologically in ascending order.*

*For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.*

*Any further corrections will be applicable from that point onwards.*

### **1 AIDS TO NAVIGATION**

Charted aids to navigation throughout the Eastern Caribbean should be used with caution. Many aids to navigation either moved or were destroyed during recent hurricanes in this region. The replacements and repositioning of these aids is progressing slowly. Yachtsmen are advised to use visual navigation. (Street 2018) (ILNW 574/18)

### **2 Bridgetown North (Plan C)**

Delete:

Or con Lt buoy FI (PA) in 13°07'·05N 59°38'·91W

Or spherical Lt buoy FI in 13°07'·21N 59°38'·69W

OrW spar Lt buoy FI in 13°07'·29N 59°38'·70W

Or con Lt buoy FI in 13°07'·41N 59°38'·71W

Y pillar Lt buoy FI.Y.2s in 13°07'·39N 59°38'·40W

Y con Lt buoy FI in 13°07'·08N 59°38'·51W

The diffuser in 13°06'·93N 59°38'·92W is no longer buoyed. Delete assoc lgd (*buoyed*) (ILNW 342/20)