

# Imray Correction Notice

ICD12

18 September 2018

## Chart D12 WGS 84

*Edition 2007*

*Versions available:*

*New Edition (Corrected to April 2007)*

**NOTE** Below is a complete list of corrections issued since the 2007 edition of this chart was published.  
Corrections are listed chronologically in ascending order.

### 1 Isla de Margarita, Pta Ballena (Main chart)

Amend Lt to Fl.10s30M in  $10^{\circ}59' \cdot 86N$   $63^{\circ}46' \cdot 65W$ .

(Plan A) Amend Lt to Fl.10s249ft30M in  $10^{\circ}59' \cdot 86N$   $63^{\circ}46' \cdot 65W$  (ILNW 417/07)

### 2 Venezuela, Cumana

Insert Lt Fl.12s61m25M in  $10^{\circ}27' \cdot 9N$   $64^{\circ}10' \cdot 0W$  (ILNW 1/08)

### 3 Isla de Margarita westwards, Bajo Ostial

Insert W card pillar Lt buoy Q(9)10s in  $11^{\circ}03' \cdot 1N$   $64^{\circ}28' \cdot 8W$ .

Delete Lt VQ(9)10s4M close by. (ILNW 37/09)

### 4 Isla de Margarita, Ensenada La Guardia eastwards (Correction amended - see ILNW 444/13)

Insert Lt Fl(2)12s39ft14M in  $11^{\circ}03' \cdot 0N$   $64^{\circ}00' \cdot 9W$  (ILNW 69/09)

### 5 Isla de Margarita, Pta Mosquito

Insert racon sym and assoc. Igd Racon(M) at Lt in  $10^{\circ}53' \cdot 1N$   $63^{\circ}53' \cdot 7W$  (ILNW 83/09)

### 6 Isla Cubagua, Pta Brasil (Correction amended - see ILNW 492/13)

Amend radar beacon at Lt from Racon(G) to Racon(M) in  $10^{\circ}49' \cdot 9N$   $64^{\circ}12' \cdot 6W$  (ILNW 91/09)

### 7 Isla de Margarita northeastwards, Los Frailes

Insert Racon sym and Igd Racon(K) at Lt in  $11^{\circ}11' \cdot 7N$   $63^{\circ}44' \cdot 2W$  (ILNW 33/10)

### 8 Porlamar (Inset)

Dinghy stealing is reportedly rife in this area. Mariners are advised to hoist dinghies out of the water at night, and keep them under lock and chain during the day. (ILNW 86/10)

### 9 Cumana (Plan G)

Cumana marina, which in the past had a good reputation, is reportedly in a rundown condition. (ILNW 87/10)

### 10 General Notice

Before visiting this area, mariners are advised to check [www.safetyandsecuritynet.com](http://www.safetyandsecuritynet.com).

The Venezuelan HO changes light characteristics on a regular basis, making it difficult to keep corrections up to date. Lights are seldom moved, but characteristics are regularly changed. (ILNW 138/10)

### 11 Isla Coche, Pta El Botón northeastwards

Insert Lt Fl.10s230ft20M in  $10^{\circ}47' \cdot 3N$   $63^{\circ}59' \cdot 2W$  (ILNW 242/10)

### 12 Isla de Margarita east coast (Correction amended - see ILNW 26/12)

Insert Lt Oc.6s49ft11M in  $11^{\circ}07' \cdot 0N$   $63^{\circ}50' \cdot 6W$  (ILNW 342/10)

### 13 Isla de Margarita, Cabo Negro (correction amended - see ILNW 310/11)

Amend Lt Fl.10s217ft11M to Fl.10s230ft19M in  $11^{\circ}10' \cdot 48N$   $63^{\circ}53' \cdot 05W$  (ILNW 235/11)

### 14 Isla de Margarita, Cabo Negro

Amend Lt Fl.10s230ft19M to Fl.5s230ft19M in  $11^{\circ}10' \cdot 5N$   $63^{\circ}53' \cdot 1W$  (ILNW 310/11)

### 15 Isla de Margarita, Morro de Robledal

Amend Lt Fl.10s262ft11M to Fl.7·5s262ft19M in  $11^{\circ}02' \cdot 60N$   $64^{\circ}22' \cdot 96W$  (ILNW 25/12)

### 16 Isla de Margarita east coast

Amend Lt Oc.6s49ft11M to Fl.6s49ft11M in  $11^{\circ}07' \cdot 0N$   $63^{\circ}50' \cdot 7W$  (ILNW 26/12)

### 17 Isla de Margarita, Pta Maria Libre southwards

Amend Lt Fl(2)12s39ft14M to Fl.8s39ft14M in  $11^{\circ}03' \cdot 0N$   $64^{\circ}01' \cdot 0W$  (ILNW 444/13)

### 18 Isla Cubagua, Pta Brasil

Amend radar bn at Lt Racon(M) to Racon(G) in  $10^{\circ}49' \cdot 9N$   $64^{\circ}12' \cdot 6W$  (ILNW 492/13)

**19 Cumana (Plan G)**

Insert:

drying wk in  $10^{\circ}27'8N$   $64^{\circ}11'6W$

dangerous wk in  $10^{\circ}27'6N$   $64^{\circ}11'57W$  (ILNW 54/14)

**20 Cumana westwards**

Insert lit platform in  $10^{\circ}26'45N$   $64^{\circ}13'97W$  (ILNW 87/14)

**21 Isla de Margarita W, Morro del Robledal**

Insert Lt Fl.8s269ft18M in  $11^{\circ}02'60N$   $64^{\circ}22'63W$ . (*Correction superseded – see ILNW 497/16*)

Delete Lt Fl.7·5s262ft19M close W. (ILNW 54/16)

**22 Punta de Piedras (Main chart & Plan E)**

Amend South Cardinal Lt buoy **Pta de Piedras** to VQ(6)+LFI.10s in  $10^{\circ}53'40N$   $64^{\circ}05'73W$ . (ILNW 269/16)

**23 Isla de Margarita (Main chart & Plans B & E)**

**Main chart & Plan B:**

**Porlamar N** Insert Lt Fl.10s12M in  $10^{\circ}58'49N$   $63^{\circ}49'11W$

**Main chart & Plan E:**

**Pta de Piedras E** Insert Lt Fl.10s11M in  $10^{\circ}53'93N$   $64^{\circ}05'71W$

**Main chart:**

**I.Blanco** Amend Lt from Fl.4s5M to Fl.4s6M in  $10^{\circ}57'84N$   $63^{\circ}47'50W$  (ILNW 463/16)

**24 Isla de Margarita W (Correction superseded - see ILNW 339/18)**

Delete Lt Fl.8s269ft18M in  $11^{\circ}02'6N$   $64^{\circ}22'6W$  (ILNW 497/16)

**25 Cumana W**

Delete:

Lit platform in  $10^{\circ}26'45N$   $64^{\circ}13'97W$

YBY West pillar Lt buoy Q(9)15s in  $10^{\circ}27'14N$   $64^{\circ}12'24W$  (ILNW 505/16)

**26 Carupano**

Insert Lt Fl.9s180ft24M in  $10^{\circ}40'2N$   $63^{\circ}15'0W$

Amend Lt to Fl.G.4s9M in  $10^{\circ}40'7N$   $63^{\circ}14'7W$ . Delete Lt Fl.9s190ft24M close SE. (ILNW 535/16)

**27 Pta El Morro (Main chart & Plan C)**

Insert Lt Fl.10s11M in  $10^{\circ}56'90N$   $63^{\circ}49'00W$  (Main chart)

Insert Lt Fl.10s197ft11M in  $10^{\circ}56'90N$   $63^{\circ}49'00W$  (Plan C) (ILNW 36/17)

**28 Isla de Margarita NE**

Insert dangerous Wk sym. & assoc. Igd Rep. in  $11^{\circ}14'0N$   $63^{\circ}44'0W$

**Isla de Margarita NW**

Delete Igd Shoaling Reptd centred on  $11^{\circ}04'2N$   $64^{\circ}28'5W$  (ILNW 51/17)

**29 Isla de Margarita W**

Insert Lt Fl.8s269ft18M in  $11^{\circ}02'6N$   $64^{\circ}22'6W$  (ILNW 339/18)

**30 NOTICE TO MARINERS**

This chart is no longer supported with notice to mariner corrections. No future notice to mariner corrections will be issued against this chart. (ILNW 465/18)