

Imray Correction Notice

05 August 2010

Chart 2100+1 WGS 84

Edition Apr 2007

Date of printing Apr 2007

The following corrections should be noted:

1 Foulger's Gat

Move **Long Sand Outer** Lt buoy to 51°35'·90N 01°26'·00E (ILNW 156/07)

2 Thames Estuary

Delete Bell at **Barrow No. 3** Lt buoy in 51°42'·02N 01°20'·24E (ILNW 180/07)

3 N Foreland, Longnose Ledge

Substitute R bn with topmark F.I.R.2M for N card buoy in 51°23'·93N 1°25'·68E (ILNW 232/07)

4 Sunk Precautionary Area & TSS

As part of the new Sunk TSS, **Kentish Knock** E card Lt buoy has been moved to 51°38'·09N 01°40'·43E. Full details of the Sunk TSS as it affects this chart will be included on the next printing. (ILNW 242/07)

5 Maplin Sands

Delete Lts Iso.G at **Blacktail W** in 51°31'·46N 0°55'·20E and at **Blacktail E** 51°31'·80N 0°56'·47E (ILNW 343/07)

6 Maplin Sands eastwards

Delete E card Lt buoy **Maplin** in 51°34'·01N 1°02'·32E.

Insert G con Lt buoy with topmk **Maplin** Q.G in 51°33'·66N 1°01'·59E (ILNW 478/07)

7 Whitstable Harbour

Delete F.R.5M(occas) at Lt in 51°21'·84N 1°01'·58E (ILNW 26/08)

8 North Foreland

Insert racon sym and lgd AIS at **LT HO** in 51°22'·49N 1°26'·71E (ILNW 40/08)

9 Approaches to the Swale (NO LONGER VALID - see ILNW 372/08)

(ILNW 56/08)

10 Approaches to the Swale (NO LONGER VALID - see ILNW 372/08)

(ILNW 164/08)

11 Oaze Deep

Move **Oaze Bank** Lt buoy to 51°29'·36N 0°56'·95E (ILNW 203/08)

12 Thames Estuary

Delete Whis at **Outer Tongue** Lt buoy in 51°30'·73N 1°26'·40E (ILNW 204/08)

13 Tizard Bank, South Edinburgh Channel and Shingles Patch

Insert depth 1·6m enclosed by 2m contour in 51°33'·46N 1°13'·03E and delete depth 3m close by.

Insert depth 1·9m enclosed by 2m contour in 51°32'·29N 1°13'·46E and delete depth 3·3m close by.

Insert drying height -0·7m in 51°33'·00N 1°16'·58E and extend Shingles Patch drying area northwards to enclose. Delete depth 7·5m close by. (ILNW 227/08)

14 Approaches to the Swale (NO LONGER VALID - see ILNW 372/08)

(ILNW 243/08)

15 Whitstable Harbour

Delete Lt F.8M in 51°21'·84N 1°01'·58E (ILNW 276/08)

16 Approaches to the Swale (Correction amended - See ILNW 424/08)

As of 1st August 2008, the trial of synchronised buoy lights has been concluded. The following Lt buoys have been removed:

Swale 1, Swale 2, Swale 4, Swale 5, Swale 6, Swale 7, Swale 8 and S Oaze.

The following Lt buoys now display a Lt characteristic of Fl.G.2s:

Columbine, Columbine Spit, Ham Gat, Sand End, Receptive and Whistable Street.

In addition, **Pollard Spit** Lt buoy has reverted to Q.R. (ILNW 372/08)

17 Approaches to the Swale

Further to previous notification about the conclusion of synchronised Lt buoy trials, the following changes to Lt characteristics have been made:

Columbine Spit Fl(3)G.10s in 51°23'·86N 1°00'·03E

Ham Gat Q.G in 51°23'·08N 0°58'·32E.

In addition, **Sand End** has reverted back to Fl.G.5s. (ILNW 424/08)

18 West Barrow southwestwards

Delete *Bell* at **SW Barrow** Lt buoy in 51°32'·29N 1°00'·31E (ILNW 605/08)

19 Princes Channel

A new southern access route to the Thames Estuary has been established in the Princes Channel. Full details of this route will be included in the next printing of this chart. In the meantime, mariners should be aware of the following buoyage changes.

Insert Lt buoys:

G con buoy **Princes N** Q.G in 51°29'·25N 1°18'·35E

Y pillar buoy with x topmk **Princes Mid** Fl.Y.5s in 51°29'·20N 1°09'·00E

Y pillar buoy with topmk **Princes Inner** Fl.Y.2·5s in 51°29'·60N 1°03'·47E

Move Lt buoys:

Princes 5 Fl(3)G.10s to 51°29'·39N 1°10'·00E

E Redsand Fl(2)R.5s to 51°29'·14N 1°04'·05E and rename **Princes 8**

Amend Lt buoys:

Princes VQ.R to **Princes S** Q.R in 51°28'·74N 1°18'·26E

Princes 1 Q.G to **Princes 1** Fl(4)G.15s in 51°29'·23N 1°16'·02E

Delete Lt buoy:

Princes Approach Mo(A)10s in 51°28'·32N 1°23'·75E (ILNW 607/08)

20 North Foreland northeastwards

As of late February 2009, construction of the Thanet Offshore Wind Farm is underway.

Insert pecked line to mark safety zone, bounded by the following positions, plus Lt buoys as indicated:

51°27'·90N 1°38'·72E [bottom edge of Tidal Diamond table]

51°26'·89N 1°40'·44E (N card Q)

51°26'·22N 1°40'·90E [E extent of chart]

and

51°23'·85N 1°40'·90E [E extent of chart]

51°23'·77N 1°40'·82E (S card VQ(6)+LFl.10s)

51°24'·33N 1°37'·12E (W card VQ(9)10s)

51°26'·58N 1°34'·17E

51°27'·65N 1°36'·07E

51°27'·90N 1°36'·87E [bottom edge of Tidal Diamond table]

Insert lgd *Wind Farm under construction (2009)* within this zone. (ILNW 82/09)

21 Thames Estuary, Tongue Sand eastwards

Delete safe water Lt buoy **Outer Tongue** LFl.10s in 51°30'·73N 1°26'·40E (ILNW 102/09)

22 Thames Estuary, North East Spit

Insert racon symbol, plus assoc lgd *Racon(T)*, at E card Lt buoy **NE Spit** VQ(3)5s in 51°27'·93N 1°29'·89E (ILNW 103/09)

23 Black Deep

Move Lt buoy **No3** Fl(3)G.15s in 51°41'·98N 1°25'·99E to 51°42'·41N 1°26'·48E (ILNW 148/09)

24 N Foreland northeastwards

Insert W card pillar Lt buoy **Thanet NW** Q(9)15s in 51°26'·80N 1°33'·80E (ILNW 269/09)

25 Princes Channel

Move **Princes 8** Lt buoy to 51°29'·14N 1°03'·00E (ILNW 276/09)

26 East Swin

Move **N Middle** Q Lt buoy to 51°41'·35N 1°12'·61E (ILNW 380/09)

27 Yantlet Channel

Amend Lt at **No.3** Lt buoy to Oc.10s in 51°29'·33N 0°46'·54E. (ILNW 479/09)

28 Sunk Sand

Substitute *Obsth* sym for **Sunk** (16) N card bn in 51°39'·43N 1°20'·63E (ILNW 54/10)

29 Knob Channel

Substitute *Whis* for *Bell* at **Knob** Iso.5s Lt buoy in 51°30'·69N 1°04'·28E (ILNW 123/10)

30 Whitaker Channel

A recent 2010 survey indicates changes to depths in the channel, some of which may be shoaler. Buoyage may be moved accordingly. Further details will be added as known, but in the meantime mariners are advised to contact the Crouch Harbourmaster. (ILNW 255/10)

31 Notification of New Edition

A new August 2010 edition of this chart will shortly be published. In addition to the listed corrections, this edition shows revised depths (especially in Princes Channel and Fisherman's Gat), plus the latest wind farm developments. (ILNW 308/10)