

Imray Correction Notice

ICA

18 January 2019

Chart A WGS 84

Edition 2006

Versions available:

New Edition (corrected to September 2006)

Update (corrected to October 2015)

NOTE Below is a complete list of corrections issued since the 2006 edition of this chart was published. Corrections are listed chronologically in ascending order. For update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction. Any further corrections will be applicable from that point onwards.

1 Antigua westwards, Sandy Island

Insert Lt Fl.10s10M PA in 17°06'·7N 61°55'·1W (ILNW 235/08)

2 Antigua, Cape Shirley

Delete Lt Fl(4)20M in 16°59'·9N 61°45'·0W (ILNW 236/08)

3 Leeward Islands, Gibbs Seamount eastwards (*Correction amended - see ILNW 374/12*)

Insert Y ODAS Lt buoy **Met Stn 42060** Fl(4)Y.20s in 16°30'N 63°30'W (ILNW 344/09)

4 Saint Martin

Delete Lt Fl(2)10s15M in 18°00'·9N 63°03'·6W (ILNW 518/09)

5 Isla Caja de Muertos southwards

Insert Y ODAS Lt buoy **Met Stn 42085** in 17°51'·6N 66°31'·4W. (ILNW 64/10)

6 Puerto Rico, Bahia de Guayanilla

Delete Lt Fl.2·5s8M in 17°58'·1N 66°45'·2W (ILNW 22/11)

7 Martinique, Fort-de-France

Delete Lt Fl(4)WRG in 14°35'·9N 61°04'·0W (ILNW 101/12)

8 Saba Bank

Insert dangerous wk sym, and lgd *Rep (2012) PA*, in 17°23'·4N 63°15'·1W (ILNW 259/12)

9 Martinique southwards (*correction superseded – see ILNW 150/17*)

Reduce range of Lt from 21M to 15M in 14°23'·54N 60°52'·09W (ILNW 292/12)

10 Saba Bank southwards

Move Y ODAS Lt buoy **Met Stn 42060** Fl(4)Y.20s in 16°30'N 63°30'W to 16°20'N 63°30'W. (ILNW 374/12)

11 Saint Croix, Fredericksted

Delete Lt Fl.WR.4s8/6M in 17°42'·9N 64°53'·0W (ILNW 499/12)

12 Mona I.

Insert Lt Fl.2·5s11M in 18°05'·2N 67°50'·8W (ILNW 384/13)

13 Puerto Rico, Pta Borinquen

Amend range of Lt Fl(2)15s24M to 14M in 18°30'·5N 67°08'·8W (ILNW 423/13)

14 Montserrat southwestwards

Move Y ODAS Lt buoy **Met Stn 42060** Fl(4)Y.20s in 16°20'·0N 63°30'·0W to 16°19'·9N 63°14'·4W (ILNW 92/14)

15 Isla Caja de Muertos

Amend Lt to Fl.30s10M in 17°53'·6N 66°31'·2W. (ILNW 247/15)

16 Dominica, Scott's Head

Amend Lt desc to Q.17M (Strobe Lt) in 15°12'·6N 61°22'·1W (ILNW 302/15)

17 Vieques I. E, Pta Este

Amend range of Lt to 9M in 18°08'·1N 65°16'·1W (ILNW 393/15)

18 Puerto Rico E, Cabo San Juan

Amend range of Lt to 11M in 18°22'·9N 65°37'·1W (ILNW 39/16)

19 Puerto Rico E

Amend range of Lt to 11M in:

San Juan, Pta del Morro 18°28'·3N 66°07'·4W
Pta Tuna 17°59'·3N 65°53'·1W. (ILNW 349/16)

20 Puerto Rico W, Cabo Rojo

Amend range of Cabo Rojo Lt to 11M in 17°56'·0N 67°11'·6W. (ILNW 370/16)

21 Martinique S

Amend range of Lt to 21M in 14°23'·54N 60°52'·09W (ILNW 150/17)

22 Guadeloupe, Basse-Terre

Amend Lt Q(9)9M to FI(3)9M in 16°06'·5N 61°46'·2W (ILNW 661/17)

23 AIDS TO NAVIGATION

Charted aids to navigation throughout the Eastern Caribbean should be used with caution. Many aids to navigation either moved or were destroyed during recent hurricanes in this region. The replacements and repositioning of these aids is progressing slowly. Yachtsmen are advised to use visual navigation. (Street 2018) (ILNW 574/18)