

Imray Correction Notice

ICY35-3SF

24 July 2023

Chart Y35 WGS 84 Edition 2022

Versions available:

New Edition (corrected to April 2022)

Update (corrected to January 2023)

NOTES

Below is a complete list of corrections issued since the 2022 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.

Any further corrections will be applicable from that point onwards.

1 Fountain Lake (Panel 1 & Panel 2)

Move BY N cardinal Lt Bn **D1** Q in 50°48'·56N 1°05'·69W to 50°48'·54N 1°05'·67W (ILNW 363/22)

2 Burrow Island NE (Panel 1)

Delete mooring buoy in:

50°48'·40N 1°07'·14W

50°48'·35N 1°07'·11W

50°48'·30N 1°07'·08W

50°48'·25N 1°07'·06W (ILNW 541/22)

3 Fareham Lake (Panel 2)

The following bns are now lit:

No 29 Fl.R.5s in 50°50'·23N 1°09'·03W

No 30 LFl.R.10s in 50°50'·28N 1°09'·06W

No 31 Q(2)R.5s in 50°50'·38N 1°09'·25W

No 41 Q(2)G.5s in 50°50'·41N 1°09'·22W

No 42 LFl.G.10s in 50°50'·32N 1°09'·04W

No 44 Fl.G.5s in 50°50'·20N 1°08'·94W (ILNW 57/23)

4 Fountain Lake

Insert depth:

0·5m in 50°48'·90N 1°05'·51W. Delete depth 1·5m close E (Y35-2)

1·8m enclosed by 2m contour in 50°48'·71N 1°06'·38W (Y35-1 & 2)

1·2m in 50°48'·69N 1°06'·47W. Delete depth 1·8m close SW (Y35-1 & 2) (ILNW 147/23)

5 Gosport Marina (Panel 1)

Insert:

Drying height -0·1m enclosed by 0m contour in 50°47'·98N 1°07'·24W

Depth 1·7m in 50°47'·97N 1°07'·10W. Extend 2m contour N to enclose

Replace depth 3·2m with 1·7m in 50°47'·99N 1°07'·15W. Extend 2m contour N to enclose (ILNW 162/23)

6 Gosport, Haslar Marina

There have been changes to the pontoon layout in Haslar Lake.

Insert minor G Lt star in:

50°47'·50N 1°06'·90W

50°47'·36N 1°07'·02W

These Lts mark the furthest extent of pontoons into Haslar Lake.

Delete minor G Lt star in 50°47'·44N 1°06'·96W (ILNW 201/23)