

Imray Correction Notice

ICM26-3

28 October 2024

Chart M26^{WGS 84}

Edition 2023

Versions available:

New Edition (corrected to April 2023)

NOTES

Below is a complete list of corrections issued since the 2023 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

1 Otocic Plocica & Rt Gaj (Main chart & Plan D)

Amend Lt FI(2)10s25m10M to FI(3)12s25m10M in 43°01'·85N 16°48'·95E (Main chart)

Replace rock sym with BRB isolated danger Lt bn FI(2)5s in 43°01'·59N 16°49'·68E (Main chart)

Delete restricted area centered on 43°23'·00N 16°12'·40E (Main chart & Plan D) (ILNW 157/24)

2 Rt Lašcatna

Insert assoc racon symbol and lgd AIS to Lt FI(4)15s12m8M in 43°18'·86N 16°53'·97E (ILNW 170/24)

3 U. Bacvice (Plan C)

Insert limit of obstruction pecked line joining:

43°30'·04N 16°26'·97E

43°30'·02N 16°26'·92E

43°30'·02N 16°26'·79E

Add assoc lgd *Obstn* (ILNW 180/24)

4 Drvenički Kanal, O. Kluda W (Plan D)

Insert Lt FI(2)G.4s in 43°28'·61N 16°09'·77E (ILNW 272/24)

5 Otok Koločep SE, Kanal Daksa (Main chart & Plan I)

Main chart

Amend Lt from FI.6s7m5M to FI.6s22m5M in 42°40'·1N 18°03'·5E

Plan I

Insert Lt FI.W.6s22m5M and sectors 022°- W -292° in 42°40'·21N 18°03'·36E

Delete Lt FI.W6s7m5M and sectors 023°- W -295° in 42°40'·23N 18°03'·35E (ILNW 320/24)

6 Otok Hvar, Rt Súcuraj N

Insert outfall pipe joining:

43°08'·11N 17°12'·31E

43°07'·86N 17°12'·16E

43°07'·62N 17°11'·73E (ILNW 488/24)