

# Imray Correction Notice

ICM21-1

13 March 2024

## Chart M21 WGS 84

Edition 2011

### Versions available:

New Edition (corrected to January 2011)

Update (corrected to April 2021)

Update (corrected to April 2022)

Update (corrected to April 2023)

Update (corrected to March 2024)

### NOTES

Below is a complete list of corrections issued since the 2011 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.

Any further corrections will be applicable from that point onwards.

#### 1 Syria, Al Ladhiqiyah

Amend Lts:

Fl.6s18m12M to Fl.5s18m12M in 35°35'·1N 35°43'·0E

Fl.G.5M to LFl.G.5M in 35°31'·8N 35°45'·3E (ILNW 067/11)

#### 2 Alanya Limani (Plan A)

Insert Lts:

Fl.G.5s11m5M in 36°32'·37N 32°00'·20E

Fl.R.5s11m5M in 36°32'·33N 32°00'·27E (ILNW 134/11)

#### 3 Iskenderun Körfezi, Botas Terminal

Insert Lt in 36°51'·0N 35°56'·0E and amend Igd to 2Mo(U)R.5M close by. (ILNW 135/11)

#### 4 Iskenderun Körfezi (Correction amended see ILNW 402/19)

Amend duration of Lt Fl.10s45m20M to 3s in 36°32'·2N 36°03'·4E (ILNW 154/11)

#### 5 Tripoli

Delete Lt Fl.R.5M in 34°27'·6N 35°49'·5E (ILNW 062/12)

#### 6 Mersin Limani (Plan C)

Delete Iso danger pillar Lt buoy Fl(2)W.5s5M in 36°47'·87N 34°38'·69E (ILNW 114/12)

#### 7 Mersin Körfezi, Deli Br. (correction amended – see ILNW 35/16)

Amend range of Lt Fl(2)5s17m10M to 5M in 36°43'·6N 34°54'·4E (ILNW 146/12)

#### 8 Turkey, Sancak Br. (correction amended – see ILNW 538/17)

Insert Lt Fl(3)10s12m10M in 36°07'·5N 33°23'·6E (ILNW 160/12)

#### 9 Beirut westwards

Insert Or superbuoy in 34°08'·4N 34°26'·6E (ILNW 249/12)

#### 10 Turkey, Karatas westwards

Delete dangerous wk sym in 36°02'·9N 32°36'·9E (ILNW 329/12)

#### 11 Mersin eastwards

Amend Lts F.R&F.G to Fl.R&Fl.G in 36°48'·3N 34°41'·7E (ILNW 369/12)

**12 Mersin (Plan C) (Correction amended - see ILNW 301/13)**

Add R pillar buoys with rectangular topmk in:

36°47'·70N 34°38'·70E

36°47'·85N 34°38'·88E

Add G pillar buoys with triangular topmk in:

36°47'·86N 34°39'·00E

36°47'·90N 34°38'·52E (ILNW 113/13)

**13 Mersin Limani (Plan C)**

Move pillar buoys:

R in 36°47'·70N 34°38'·70E to 36°47'·65N 34°38'·71E

R in 36°47'·85N 34°38'·88E to 36°47'·79N 34°38'·85E

G in 36°47'·85N 34°39'·00E to 36°47'·79N 34°38'·95E (ILNW 301/13)

**14 Automatic Identification Systems, Turkey**

Mariners should be aware that numerous navigational aids along the Turkish coast have been fitted with Automatic Identification System transmitters. (ILNW 476/13)

**15 Turkey, Erdemli southeastwards**

Insert Lt Fl.R&Fl.G.4s7M in 36°31'·9N 34°13'·9E. (ILNW 261/14)

**16 Cyprus N Coast, Kyrenia**

Amend Lt to Fl(3)20s18m20M in 35°20'·3N 33°19'·9E. (ILNW 72/15)

**17 Turkey South Coast, Incekum Br**

Delete Lt and assoc racon sym Fl.10s13m10M Racon (K) in 36°13'·8N 33°57'·3E. (ILNW 153/15)

**18 Automatic Identification Systems (Plan C) (Correction amended see ILNW 148/19 & ILNW 45/20)**

Insert racon sym and lgd AIS at Lt:

Fl.R.3s9m10M in 36°47'·09N 34°38'·52E

Fl.G.3s9m10M in 36°47'·23N 34°38'·55E (ILNW 177/15)

**19 Mersin Körfezi**

Insert dangerous Wk sym in 36°45'·8N 34°50'·1E (ILNW 354/15)

**20 Lebanon & Syria Approach Routes**

Lebanese and Syrian regulations require vessels entering Sidon, Beirut and Tripoli to use the approach channels.

Insert limit of approach route, pecked line joining:

**Sidon**

33°35'·0N 35°08'·0E & 33°35'·0N 35°18'·5E

33°33'·0N 35°08'·0E & 33°33'·0N 35°18'·5E

**Beirut**

33°55'·5N 35°12'·9E & 33°55'·5N 35°24'·4E

33°52'·5N 35°12'·9E & 33°52'·5N 35°24'·4E

**Tripoli**

34°31'·0N 35°31'·0E & 34°31'·0N 35°41'·8E

34°29'·0N 35°31'·0E & 34°29'·0N 35°41'·8E (ILNW 388/15)

**21 Mersin Körfezi, Deli Br. (correction amended – see ILNW 533/16)**

Amend Lt to Fl.5s17m5M in 36°43'·7N 34°54'·3E (ILNW 35/16)

**22 Mersin (Plan C)**

Move No 1 mooring buoy from 36°47'·34N 34°38'·15E 36°47'·23N 34°38'·04E (ILNW 76/16)

**23 Lebanon, Tripoli**

Delete dangerous Wk sym. in 34°30'·0N 35°49'·1E (ILNW 303/16)

**24 Hefa (Plan C) (correction deleted)**

Delete R can Lt buoy Fl(2+1)R.10s in 32°51'·43N 35°00'·65E. (ILNW 368/16)

**25 Mersin Körfezi, Deli Br. (correction amended – see ILNW 562/17)**

Insert Lt Fl(2)5s12m8M in 36°43'·8N 34°54'·7E. Delete Lt Fl.5s17m5M close SW (ILNW 533/16)

**26 Anamur Br**

Amend range of Lt to 20M in 36°01'·1N 32°48'·2E (ILNW 575/16)

**27 Antalya Körfezi**

Insert Lt Mo(U)10s11m5M Dn in 36°22'·4N 32°10'·9E (ILNW 18/17)

28 **Lebanon, Beirut** (*correction superseded – see ILNW 362/17*)  
Amend Lt desc. to Fl(6+2)10s52m22M in 33°54'·0N 35°28'·2E (ILNW 162/17)

29 **Mersin Limani (Plan C)**  
Depths within Mersin Port are reported to be less than charted. (ILNW 335/17)

30 **Lebanon, Beirut**  
Amend Lt desc. to Fl(2)10s52m22M in 33°54'·0N 35°28'·2E (ILNW 362/17)

31 **Antalya Körfezi to Taşucu Körfezi**

Amend:  
range of Lt Selinti Br. Fl.3s33m8M to 10M in 36°14'·1N 32°17'·9E  
range of Lt Sancak Br. Fl(3)10s12m10M to 5M in 36°07'·5N 33°23'·6E  
duration of Lt Bölükada Br. Fl(2)5s43m18M to 6s in 36°08'·1N 33°41'·1E (ILNW 538/17)

32 **Mersin Körfezi, Deli Br.**  
Insert racon sym and lgd AIS at Lt Fl(2)5s12m8M in 36°43'·8N 34°54'·7E (ILNW 562/17)

33 **Mersin Körfezi**  
Delete dangerous Wk sym. in 36°45'·6N 34°46'·7E (ILNW 580/17)

34 **İskenderun Körfezi**  
Amend range of Lt:  
Fl.R.9M to 5M in 36°43'·7N 36°11'·3E  
Fl.G.10M to 5M in 36°43'·4N 36°11'·1E (ILNW 488/18)

35 **İskenderun Körfezi**  
Amend Lt Fl(3)G.6s3M to Fl(3)R&G.6s3M in 36°41'·1N 36°11'·8E (ILNW 595/18)

36 **İskenderun Körfezi** (*correction amended - see ILNW 238/20*)  
Amend Lt Fl.3s7m7M to Fl.WR.3s7m5M in 36°42'·9N 35°42'·8E (ILNW 106/19)

37 **Mersin** (*Correction amended see ILNW 345/19 & ILNW 46/20*)  
Amend Lt desc Fl.R.3s9m10M to Fl.R.7M&Fl.G.10M in 36°47'·09N 34°38'·52E (ILNW 147/19)

38 **Mersin (Plan C)** (*Correction amended see ILNW 45/20*)  
Amend range of Lt Fl.R.3s9m10M to 7M in 36°47'·09N 34°38'·52E plus delete racon sym and lgd AIS (ILNW 148/19)

39 **Mersin** (*Correction amended see ILNW 46/20*)  
Amend Lt desc Fl.R.7M&Fl.G.10M to Fl.R&Fl.G.7M in 36°47'·09N 34°38'·52E (ILNW 345/19)

40 **Mersin (Plan C)** (*Correction amended see ILNW 45/20*)  
The commercial quay in Mersin Limani has been extended S.  
Move Lt F.R.2M in 36°47'·74N 34°38'·27E to 36°47'·67N 34°38'·27E plus amend desc to Fl(3)Y.8s9m3M. This marks the W head of the quay.  
Amend range of Lt Fl.G.3s9m10M to 7M in 36°47'·23N 34°38'·55E (ILNW 346/19)

41 **Râs Sarafand**  
Move Lt Fl.3s5m3M in 33°26'·3N 35°15'·7E to 33°26'·8N 35°16'·6E (ILNW 398/19)

42 **İskenderun Körfezi**  
Amend range of Lt:  
Fl.5s5M to 3M in 36°54'·3N 35°59'·0E  
Fl.5s5M to 3M in 36°54'·3N 35°59'·6E  
Fl(2)R.10s9M to 7M in 36°33'·3N 35°23'·5E  
Amend Lt desc at:  
Y can Lt buoy Fl.Y.5s to Fl(4)Y.10s in 36°53'·0N 36°03'·3E  
Lt Fl.3s45m20M to Fl(2)5s45m20M in 36°32'·2N 36°03'·4E (ILNW 402/19)

43 **Cyprus, Limassol**  
Amend range of Lt:  
Q(6)R.10s12M to 5M in 34°39'·0N 33°01'·9E  
Oc.G.7s10M to 4M in 34°39'·1N 33°01'·4E (ILNW 533/19)

44 **Incekum Br. & İskenerun Körfezi**  
Insert dangerous wreck sym. in 36°15'·2N 34°00'·4E  
Move Lt Fl(2)10s30m10M in 36°46'·7N 35°47'·9E to 36°47'·0N 35°49'·0E plus amend elevation to 40m (ILNW 692/19)

#### **45 Mersin (Plan C)**

Amend Lt:

Fl.R.3s9m7M to Fl.R.3s7m3M in 36°47'·09N 34°38'·52E plus insert racon sym & add lgd AIS  
Fl.G.3s9m7M to Fl.G.3s7m3M in 36°47'·23N 34°38'·55E plus insert racon sym & add lgd AIS  
Dir.Fl.WR.5s10m5M to DirFl.WR.5s11m5/3M in 36°47'·04N 34°38'·11E (ILNW 45/20)

#### **46 Mersin**

Amend range of Lt Fl.R&Fl.G.7M to 3M in 36°47'·09N 34°38'·52E (ILNW 46/20)

#### **47 Larnaca Bay**

Insert dangerous wreck sym. in 34°57'·7N 33°41'·5E (ILNW 98/20)

#### **48 Ayia Napa**

Insert Lt Fl.R&G.10s10M in 34°58'·70N 33°56'·92E. (ILNW 200/20)

#### **49 Iskenderun Körfezi**

Delete Lt Fl.WR.3s7m5M and assoc racon in 36°42'·9N 35°42'·8E (ILNW 238/20)

#### **50 Mersin (Plan C)**

Insert:

Drying wk symbol in 36°47'·14N 34°38'·05E  
Wk with a depth of 3.9m in 36°47'·33N 34°37'·83E (ILNW 256/20)

#### **51 Cyprus, Approaches to Larnaca**

Delete dangerous wk sym in 34°53'·6N 33°39'·6E (ILNW 539/20)

#### **52 Lebanon, Sidon**

Delete dangerous wk sym in 33°33'·5N 35°20'·9E (ILNW 543/20)

#### **53 Mersin Körfezi**

Replace Y special purpose can Lt buoy Fl(2)Y.10s (3 buoys) with a mooring buoy sym and assoc lgd (3 buoys) in 36°45'·1N 34°45'·1E (ILNW 93/21)

#### **54 Larnaca (Plan B)**

Replace B con Lt buoy Q with G con Lt buoy Fl.G.2s in 34°55'·83N 33°39'·16E (ILNW 119/21)

#### **55 Mersin (Main chart & Plan C)**

##### **Main chart**

Amend range of Lt Fl.R&Fl.G.3M to 7M in 36°47'·1N 34°38'·5E

##### **Plan C**

Amend Lt:

Fl.R.3s7m3M to Fl.R.3s10m7M in 36°47'·09N 34°38'·52E  
Fl.G.3s7m3M to Fl.G.3s9m7M in 36°47'·22N 34°38'·55E (ILNW 564/21)

#### **56 Mersin (Plan C)**

Delete G pillar buoy in:

36°47'·90N 34°38'·52E  
36°47'·79N 34°38'·95E

Delete G can Lt buoy Fl(2)G.5s in 36°47'·37N 34°38'·59E

Delete R pillar buoy in:

36°47'·79N 34°38'·85E  
36°47'·65N 34°38'·71E

Delete R can Lt buoy Fl(2)R.5s in 36°47'·44N 34°38'·37E

Delete YB S card can buoy VQ(6)+Fl.10s in 36°47'·48N 34°38'·51E

Insert R port hand pillar Lt buoy Fl(2)R.5s in:

36°47'·43N 34°38'·24E  
36°47'·65N 34°38'·71E  
36°47'·77N 34°38'·84E

Insert G starboard hand pillar Lt buoy Fl(2)G.5s in:

36°47'·89N 34°38'·55E  
36°47'·42N 34°38'·59E  
36°47'·76N 34°38'·94E

Insert RW safewater pillar Lt buoy Iso.2s in 36°47'·52N 34°38'·55E (ILNW 578/21)

#### **57 Antalya**

Amend range of Lt Baba Burnu Fl.5s35m14M to 10M in 36°50'·8N 30°45'·5E plus insert racon sym & assoc. lgd AIS at Lt. (ILNW 624/21)

**58 Mersin East Breakwater (Plan C)**

Amend Lt Fl.G.3s9m7M to Fl.G.3s7m3M and move from 36°47'·22N 34°38'·55W to 36°47'·27N 34°38'·59E (ILNW 216/22)

**59 Iskenderun S**

Amend range of Lt from Fl(2)5s45m20M to 15M in 36°32'·2N 36°03'·3E (ILNW 219/22)

**60 Alanya SE**

Amend Lt Mo(U)10s11m5M to Mo(U)10s10M in 36°22'·4N 32°10'·9E (ILNW 319/22)

**61 Alanya (Plan A)**

Amend Lt Fl.Y.5s9m5M to Fl.Y.5s8m3M in 36°32'·05N 32°00'·26E (ILNW 463/22)

**62 Mersin Körfezi**

Insert Y special purpose can Lt buoy Fl(2)Y.10s (*3 buoys*) in 36°45'·8N 34°45'·5E. Delete mooring buoy and assoc lgd (*3 buoys*) close SW (ILNW 143/23)

**63 Mersin (Plan C)**

Amend Lt from Dir.Fl.WR.5s11m5/3M to Dir.Fl.5s11m5M in 36°47'·04N 34°38'·12E. The existing W lt sector remains unchanged (ILNW 266/23)

**64 Approaches to Antalya**

Delete Y pillar Lt buoy Fl.Y.3s in 36°47'·6N 30°36'·7E (ILNW 308/23)

**65 Kemer**

Amend Lt Fl.G&Fl.R.3M to Fl(2)G&Fl(2)R.7s5M in 36°36'·2N 30°34'·4E (ILNW 319/23)