



CRUISING ALMANAC 2024

CUMULATIVE CORRECTIONS ISSUE 9.0

Cut-off date 30th April 2024

The Cruising Association, its officers, members, the editor and individual authors make no warranty as to the accuracy or reliability of any information contained in this publication and accept no liability for any loss, injury or damage occasioned to any person acting or refraining from action as a result of the use of such information or any decision made or action taken in reliance or partial reliance on it save that nothing contained in this publication in any way limits or excludes liability for negligence causing death or personal injury or for anything which may not legally be excluded or limited. No national hydrographic office, or local harbour authority has verified the information in these corrections, and none accept liability for the accuracy of reproduction or any modifications made thereafter therefore **this product should not be used for navigation**. New or amended Notices since the last Issue will be highlighted thus.

Please report any errors or omissions to almanac@theca.org.uk. Free monthly corrections by email are available by signing in at www.theca.org.uk/almanac/corrections.

General Information

p17 SHIPPING FORECASTS ON RADIO 4, Text

Amend all except final sentence to:

- 00:48 – Includes weather reports from coastal stations and an inshore waters forecast
- 05:20 – Includes weather reports from coastal stations and an inshore waters forecast
- 17:54 – Weekends Only

It will be broadcast on FM (BBC Radio 4), DAB and BBC Sounds. RE Apr24

England South Coast

p30 NEWLYN, Plan

Delete Pierhead light F.R. in 50° 06'·16N

5° 32'·82W.

NM 5032/23

p33 FALMOUTH HARBOUR, Plan

Eastern Breakwater E: **Insert** Y special purpose pillar Lt buoy Fl.Y.5s in 50°09'·33N 5°02'·55W ILNW 108/24

p34 FALMOUTH, Plan

Penryn River **Insert** pontoon joining 50°09'·96N

5°04'·84W 50°09'·94N 5°04'·69W.

ILNW 483/22

p45 BRIXHAM, Plan

Insert: Minor R Lt in 50°24'·03N 3°30'·89W

Delete Lt Q.G in 50°23'·86N 3°30'·65W

Insert pontoon and minor G Lt joining: 50°23'·90N

3°30'·63W & 50°23'·87N 3°30'·63W ILNW 131/24

p46 TEIGNMOUTH HARBOUR, Plan

Insert depth 1·1 in 50° 32'·37N 3° 29'·46W.

NM4180/22

p47 TEIGNMOUTH Text Col 3

Replace There is ... 265° by:

There is a dredged channel, (least depth 1·0m) marked by a Ldg line (Lucette Lt Oc.R.6s on the training wall on the left of the entrance with vertical W stripe on the sea wall or two vertical R lights) on 264°/084°. RE

p48 RIVER EXE, Plan

Insert depth, drying ht 0·6, and extend approximate 0m low water line SE to enclose, in 50° 36'·26N

3°24'·01W.

NM1822/24

p49 **WEST BAY (BRIDPORT)**, Plan

Insert depth, 0.2 in 50° 42'·56N 2° 45'·84W.

Delete depth, 1.6 , close by. NM 2002/24

p50 **PORTLAND HARBOUR**, Plan

Amend light-buoy to, Mo(A)8s in 50° 35'·20N

2° 27'·25W. NM 379/24

p52 **SWANAGE**, Plan

Latitude scale has been amended. For amended plan [click here](#). ILNW Feb2024

p52 **APPROACHES to POOLE** , Plan & Text line 10 ,
Insert The Studland No Anchoring Zone is now marked with yellow marker buoys, details PHC LNTM 08/24

<https://www.phc.co.uk/wp-content/uploads/2024/03/2024-08-Studland-Bay-Voluntary-No-Anchoring-Zone.pdf> RE 3/24

p56 **NEEDLES CHANNEL**, Text

Insert in Col 4. The sandbank NE of Hurst Point is rapidly changing. Small craft are advised to give Hurst Point a wide berth. ILNW 96/2023

p57 **YARMOUTH**, Text

Entrance; Insert, Line 13. Some of the visitors' buoys N of the breakwater are in shallower water than shown on the chart and in the Harbour Guide. Parts of the western end of the middle trot (9-12m LOA) have only about 0.5m at CD. Deepest water is to the east. If in doubt, call the HM. RE August 2023

p69 **LANGSTONE HARBOUR**, Plan

Insert Con G buoy FL.G *Mulberry* in 50° 47'·82N., 1° 01'·64W. NM 3332/23

Insert BRB Isolated Danger buoy Fl.2s in 50° 48'·11N 1° 01'·51W which is close NE of Turbine. NM4696/23

p75 **NEWHAVEN** Plan

Amend light at LT HO from Oc(2)10s17m12M to, Iso.4s17m12M in 50° 46'·55N 0° 03'·51E NM 882/23

p76 **EASTBOURNE – SOVEREIGN HARBOUR**, Plan

Delete G buoy Fl.G.3s in 50° 47'·37N 0° 20'·21E. NM 659/23

p77 **DOVER HARBOUR**, Plan

Delete pier-head light Fl(2)R.5s in 51° 07'·50 N 1° 20'·28 E. NM1085/23

England East Coast

p83 **THAMES ESTUARY PASSAGES** Plan

On or about 17/05/2024, the following operations to buoyage will take place.

Long Sand Head N card buoy, VQ, Bell to be moved to 51° 48'·37N 01° 38'·16E

East Long Sand Head New station to be deployed in 51° 48'·12N 1° 39'·39E with E card buoy, BYB, Q(3) 10s, AIS. TH 5/2004

p88 **RIVER THAMES**, Tex, Col 4 Line 20,

Limehouse Dock Marina Replace text “ No visitors . . . with” :

Visitor berths are usually available. Contact the marina office 0207 308 9930 well before arrival, when you reach Limehouse call again on VHF 80. Berthing normally on pontoon H, max draft 2m. This is the headquarters of the CA, with its club house, library overlooks the basin and welcomes visitors. Ed

P92 **RIVERS CROUCH AND ROACH**, Plan

Insert Y Sph buoy Ray Sand North in 51° 40'·81N 1° 00'·57E.

Y Sph buoy Ray Sand in 51° 39'·84N 1° 00'·57E.

Delete W sph buoy Ray Sand 51° 39'·08N., 0° 59'·28E. RW buoy Ray Sand Middle in 51° 40'·00N., 0° 59'·00E. RW buoy Ray Sand North in 51° 40'·70N., 0° 59'·50E

p 96 **WALTON BACKWATERS**, Text

Col4, line5: **Replace** “Channel on plan.” with “ After about 1M, at the unlit N card buoy, the deep water channel curves to the West and Titchmarsh Marina. Or to the South, at HW -0300, for draft 1.6m, a narrow buoyed channel leads to WFYC where a quay can be used HW -0200 to HW. “ Ed

p 97 **WALTON BACKWATERS**, Inset Plan

Insert N Card buoy (unlit) in 51° 51'·85 N 1° 16'·20 E. Ed

p99 **RIVER ORWELL**, Text

Pin Mill Insert in line 6: For visitor's mooring Harry King (boatyard) 01473 780258, or 07867 640650. Facilities: no fuel. Ed

p99 **IPSWICH**, Text

NEPTUNE and **IPSWICH HAVEN** Marinas are now one organisation **IPSWICH BEACON MARINA**, Tel 01473 236644. VHF 80. Facilities unchanged. Ed

p102 **ORFORD HAVEN**, Text

Col2 **Facilities** line 4: Delete “Orford garage (½M) or” Ed

p103 **LOWESTOFT**, Text

Col 1 line 4 Insert Two white, lit, rectangular marks have been built in 52°27'·64N 1°44'·61E Fl.Y 5s and In 52°27'·72N 1°45'·82E Fl.Y 2·5s HM .

p104 **NORFOLK BROADS**, Text

Insert Mariners are advised that Haven Bridge is currently not able to lift due to technical issues.
Peel Ports 38/2023

p105 **BLAKKENEY MARBOUR**, Plan

Amend light on Fairway Marker buoy to L.Fl.10s in 52° 59'·23 N 0° 58'·54' E

Replace existing No.2,4,6,5,7,8 and **Insert**
No. 1 stb buoy Fl.G 2s in 52° 58.91 N 0° 58.4 E
No.3 stb buoy Fl.G 2.5s in 52° 58'·86 N 0° 58'·26 E
No. 5 stb buoy Fl.G 5s in 52° 58'·87 N 0° 57'·98 E
No. 9 stb buoy Fl.G 2·5s in 52° 58'·78 N 0° 57'·53 E
No.10 port buoy QFl.R in 52° 58'·73 N 0° 57'·55 E
BHA Mar 24

p107 **APPROACHES TO KING'LYNN AND WISBEECH**

Plan. **Delete** spherical Y Buoy Fl(5)Y.20s in 52° 56'·50N 0° 19'·10E. NM1069/24

p109 **RIVVER HUMBER ENTRENCE**, Plan

Insert depth 2·6 in 53° 35'·95N 0° 00'·30E.
NM1353/24

p114 **SEAHAM**, Plan

Amend light at North Pier head to Fl(4)G.10s10M in 54° 50'·26N 1° 19'·25W. NM800/24

p114 **RIVER TYNE**, Text

St Peter's Marina : **Tel** Insert 07498 863198.
VHF replace 37,80 with 13. Marina 4/2024

p114 **BLYTH**, Text

Approach Line 5,
Delete There are Ldg . . . diamond topmarks.
Insert There is a light DirWRG.4s10M in 55° 07'·44N 1° 29'·84W. Enter on the narrow W sector on 324°.

p115 **BLYTH**, Plan

Delete leading lights F.Bu in 55°07'·50N 1°29'·91W, and 55°07'·42N 1°29'·82W and associate leading line 324°and legend 324°.
Insert Lt Dir.WRG.4s14m10M with assoc Lt sector 322°-Iso.G-324°-Al.GW-325°-Iso.W-327°-Al.RW-328°-Iso.R-330° in 55° 07'·44N 1°29'·84W. ILNW 392/23

p117 **BERWICK**, Plan

Insert light Fl.G.3s on No.3 G con buoy in 55° 45'·73N 1° 60'·00W NM 2023/24

East and North Scotland Coasts

p119 **BERWICK TO ARBROTH**, *Passage Lights*
Isle of May , amend Range from 22M to 18M. NL09

p123 **RIVER TAY Continuation**, Plan

Insert E card buoy VQ(3)5s in 56° 27'·60N 2° 57'·16W and delete legend 2Bns close W of above
NM247/23

p125 **PETERHEAD** Plan

Replace depth 2·4, with depth 1·6, and extend 2m contour E to enclose in 57° 30'·51N 1° 46'·24W.
NM3443/22

p127 **BUCKIE**, Plan

Amend light to, Fl.G.2s5m4M in 57° 40'·81N 2° 57'·65W. NM3732/23

Amend light to, Fl.R.2s6m4M in 57° 40'·83N 2° 57'·71W . NM776/24

Insert minor R Lt in 57°40'·82N 2°57'·58W G Lt in 57°40'·80N 2°57'·57W ILNW 43/24

p128 **BURGHEAD**, Plan

Amend range of light to 2M, in 57° 42'·11N 3° 29'·93W and range of light to 3M, in 57° 42'·08N 3° 30'·03W. NM4582/23

Insert new pier lights:

Fl.R.4s 4m2M in 57° 40'·82N 2° 57'·58W
Fl.G.4s 3m2M in 57°40'·80 N 2° 57'·57W NM536/24

p128 **CALEDONIAN CANAL**, Text

Amend Tel Clachnarry Sea Lock to 01463 725512, or 07920 237331. Ed

p135 **SHETLAND**, Fair Isle, Plan

Amend range of North Skroo light in 59° 33'·13N 1°36'·59W, from 22M to 18M . NL 14/22

Scotland West Coast

p145 **ISLE OF ORNSAY**, Plan

Insert unlit Y bns in 57° 08'·65N 5° 47'·95W and 57° 08'·68N 5° 47'·52W with underground electric cable between them. NM457/24

p157 **STORNOWAY**, Plan

Delete depth 6·8m and surrounding dotted circle in 58° 11'·86N 6° 22'·80W. NM4143/23

p161 **CAMBLETOWN**, Plan
Insert depth: 0.8m in 55°25'·88N 5°33'·60W and
extend 2m depth to enclose. ILNW 177/22

p164 **TROON**, Text
Depths shown within Troon Harbour are subject to
siltation and liable to change. For the latest
information, consult HM. ILNW 86/24

p164 **LOCH RYAN**, Plan
Delete light Bns
Oc.G.6s No 1 in 54° 56'·68N , 5° 01'·32W.
F.G.3s No 5 in 54° 55'·09N., 5° 01'·86W.
Q.G No 3 in 54° 55'·88N., 5° 01'·59W. NM1005/24

p164 **LOCH RYAN**, Text, cols 3 and 4
Stranraer Marina:- **Delete**:- three G Lt bns mark the
W side of the channel leading into Stranraer Hbr and
marina.
Inserts:- from the Spit G con buoy Fl.G.6s steer for a
point slightly NW of Stranraer from where entry can
be made to the marina.
The Wig:- **Delete**:- passing midway between
Spit G con buoy Fl.G.6s and No.1 bn Oc.G.6s.
Insert:- turning S 0.3M S of Spit G con
buoy Fl.G.6s., then make good a suitable course to the
anchorage. RE

England West Coast and Wales

p173 **FLEETWOOD HARBOUR**, Plan
Amend light to,
Iso.4s in 53° 55'·59N., 3° 00'·46W and light to,
Iso.2s in 53° 55'·72N., 3° 00'·55W

p175 **LIVERPOOL, RIVER MERSEY** Plan
Insert Lt on quay 2F.R(vert) in 53° 24'·74N
3° 00'·18W. NM 937/2024

p180 **HOLYHEAD**, Plan
Amend fog signal Siren 20s to Horn 20s at Lt in
53°19'·85N 4°37'·16W ILNW 231/23

p183 **FISHGUARD**, Text
Tel/VHF Old Harbour. **Amend** HM 01348 873389 to
HM office 01834 842717. RE

p186 **MILFORD HAVEN ENTRANCE**, Plan
Insert AIS at Mid Channel Rocks W Card light buoy in
51° 40'·17N 5° 10'·10W NM462/2024

p187 **MILFORD HAVEN, Central Section**
Amend Outfall light-buoy to, VQ in 51° 41'·75N
4° 59'·74W NM 4970/22

p188 **NAVIGATION IN THE BRISTOL CHANNEL**
Nash Point: **Amend** range, white to 19M and red to
14M TH41/22
Trevoose Head Amend range to 18M Ad Lt List 10/23

p195 **PADSTOW**, Plan
Move G lighted buoy Fl.G.5s Doom Bar from
50° 33'·59 N 4° 56'·23 W to 50° 33'·51N 4° 56'·31 W
Move R lighted buoy LFl.R.10s Daymer from
50° 33'·50 N 4° 56'·39 W to 50° 33'·49N 4° 56'·20 W
Move G lighted buoy Fl.G.10s Gun Pt from
50° 33'·26N 4° 56'·24 W to 50° 33'·27 N 4° 56.25 W
Insert Wreck buoy symbol Fl(2).G.5s Antoinette in
50°33'·81 N 4° 56'·17' W and **Delete** existing wreck
buoy Fl(2).10s close SW. ILNW11/2023

Ireland

p201 **VALENTIA**, Plan
Insert W card buoy YBY Q(9)15s in 51° 56'·71N
10° 17'·49W and delete isolated danger mark Fl(2)6s
close by. NM2649/23

p211 **CORK HARBOUR**, Plan
Insert light 2F.R(vert)3m1M in 51° 50'·12N
8° 18'·26W. NM1658/24

p212 **CORK TO TUSKAR ROCK**, Passage Lights
Tuskar Rock
Amend range of Lt Q(2)7·5s33m24M to 18M
ILNW 384/22

p214 **WATERFORD HARBOUR**, Plan
Insert spherical Y buoys Fl.Y.6s in 52° 15'·55N
7° 02'·07W and in 52° 16'·00N 6° 58'·72W. NM547/24
Move Lt Fl(3)R.10s6m4M from 52°08'·98N 6°59'·40W
to 52°08'·99N 6°59'·39W ILNW 323/23

p215 **WATERFORD**, Text
Waterford City Marina will be closed to visitors until
2025. Works in progress. City Council

p218 **DUBLIN BAY**, Plan
Move No 1 G con buoy to 53° 20'·27N 6° 05'·26W
NM3016/23
Delete Y buoy with top mark, Q(5)20s and AIS in
53° 21'·32N 6° 05'·37W. NM1036/24

p218 **BELFAST**, Plan

Amend light to, Fl.Y jn 54° 36'·34N 5° 54'·90W.

Delete pier light 2F.G (vert) in 54° 36'·27N 5° 55'·18W
NM1906/2023

p219 **HOWTH**, Plan

Amend range of Lt Fl.G.3s6M to 3M in 53°23'·53N
6°04'·08W ILNW 291/23

p231 **BURTONPORT**, Text

Col 1 line 7. After 081487 6482 **insert** or 0873
354831, main office 0868 310121. Ed 9/23

p240 **CASHLA BAY**, Plan

Insert depth 0·8 m in 53° 16'·50N., 9° 33'·87W and
extend 2m contour SW to enclose. NM3589/23

Insert con G buoy Fl.G.2s in 53° 15'·84N 9° 02'·43W
NM436/24

p240 **GALWAY**, Plan

Insert G con Lt buoy with topmark Fairway Buoy No 3
Fl.G.2s in 53°15'·84N 9°02'·43W ILNW 35/24

p241 **KILRONAN HARBOUR**, Text

Anchorage Insert: Easy access; keep clear of ferries.Ed

p243 **DINGLE HARBOUR**, Plan

Amend range of Lt DirOc.WRG.4s13m2M to 3M in
52°08'·33N 10°16'·52W ILNW 414/22

Belgium

p245 **NIEUPOORT**, Plan

Amend range of light at pierheads to 11M in
1° 09'·35N 2° 43'·00E and 51° 09'·42N 2° 43'·08E.
NM1475'24

p245 **OOSTENDE**, Plan

Amend Range of light in 51°14'·19N 2°55'·79E from
27M to 22M. NM 4828/23

Amend Range of light in 51°13'·80N 2°55'·89E from
4M to 18M

Amend Height and Range of light in 51°13'·63N
2°56'·10E from 46m 4M respectively to 50M and 18M.
NM514/24

Amend range of light at pierhead to, 11M 51°
09'·35N., 2° 43'·00E.
51° 09'·42N., 2° 43'·08E.

p246 **ZEEBRUGGE**, Plan

Delete Lt F.G in 51°20'·39N 3°11'·74E ILNW 234/23

Netherlands

p255 **STANDING MAST ROUTE**, Text

Col 1, line 4: **INSERT** "local time" after "0200".

Col 1, At end of 1st paragraph insert "Amsterdam rail
bridge not operating from 1st Oct 2023 until 31st
May 2024 for vessels with more than 6.25 m above
normal canal level. Use the Haarlem route instead."

p257 **APPROACHES TO THE WESTERSCHELDE**, Plan

Insert R can Lt buoy SS 2 Q.R in 51°25'·50N 3°37'·92E.

Delete R spar buoy SS 2 close to NW Replace G
starboard spar buoy SS 5 with Y special pillar buoy
ARV 5 in 51°24'·71 N 3°38'·04E

Delete G starboard spar buoy SS 3 in 51°25'·04N
3°37'·30E.

Delete R can Lt buoy SS 4 Q.R in 51°25'·23N 3°37'·82E
ILNW 304/22

p259 **ENTRANCE TO THE OOTTERSCHDELDE**, Plan

Replace light and designation of bn **WG4** to Fl(5)Y20s
OS11 in 51° 38'·62N 3° 28'·88E. NM514/24

Approaches to the Baltic

p281 **INTRODUCTION, Fuel**

Lines 4 – 6. **Replace** "Diesel sold the Baltic"
by "All diesel sold for marine use will contain some
bio-diesel". RE 1/2024

p293 **EGERSUND**, Plan

Ruskodden light sectors changed: From offshore N
sector G sector changed to R. White sector
unchanged. R sector changes to G. ww.norgeskart.no

p304 **LAGUNEN YACHT HARBOUR**, Plan

Latitude scale. **Insert** 12° before 56'·0 RE11/2023

p306 **WARNEMUNDE** Plan

Insert E card buoy, BYB, in 54° 11'·05N 12° 05'·26E.
NM2971/23

France North Coast, and Channel Islands

p316 **DUNKERQUE**, Plan

Move G con buoy Q.G DW29 to 51° 03'·81N
2°20'·20E. NM3541/23

p317 **CALAIS TO LE HAVRE**, Passage Lights

Replace Cap de Alprech . . . with
Le Toucet 1196
Fl(2)10s54m25M RE

p320 **ST-VALERY-EN-CAUX**, Plan

Amend height of stb pierhead light from 13m to 12m.
NMWk43Lt List

p321 **FECAMP**, Plan

Amend light to Fl(2) 6s 15m 12M at Jetée Nord, Head
in 49° 45'·92 N 0° 21'·80 E NM 4692/23

p327 **BARFLEUR**, Plan

Insert lit mooring buoy sym. Fl.Y.4s in 49°40'·50N
1°15'·68W ILNW 83/24

p328 **CHERBOURG**, Plan

Delete light Q.16m13M in 49°39'·06N 1°36'·01W
ILNW 471/22

p329 **PASSAGE LIGHTS**, Guernsey

Platte Fougère Delete Racon(P) ILNW 354/23
Insert AIS NM Lights List 15/24

p338 **ST MALO APPROACHES**, Plan

Insert rock which covers / uncovers sym. in
48°39'·48N 2°01'·71W ILNW204/23

Delete unlit R buoy with top mark No4 Bell in
48° 40'·24N 2° 07'·20W NM4444/23

Delete R can buoy No 6 in 48°40'·26N 2°06'·13W

Amend Light of pillar buoy No 2 from No 2 from
Fl.R.4s to Fl.R.2·5s in 48°40'·24N 2°07'·35W.
ILNW 356/23

p341 **RIVER RANCE**, Text

Col 1: Plouër Marina. **Amend** "10 visitors' berths" to
"visitors usually berth on B pontoon, best to call HM".
Delete "two waiting pontoons outside marina". Ed

p341 **ST-CAST-LE-GUIDO**, Text

Col 2: Approach At end, insert "there are numerous
fishing floats in the approaches, extreme caution
advised at night." Ed

p341 **ST CAST**, Plan,

Longitude Scale. **Amend** 15.5' to 14'·5 . Ed

p345 **RIVIERE DE TREGUIER**, Plan

Insert rock awash sym in 48°52'·05N 3°09'·21W .

Delete fog signal, *Whis*, at light-buoy, Basse Crublent,
in 48° 54'·28N 3° 11'·15W. NM3951/23

Move R can Lt buoy Le Corbeau from 48°53'·37N

3°10'·25W to 48°53'·29N 3°10'·11W

Move G con Lt buoy Pierre à l'Anglais from 48°53'·20N

3°10'·43W to 48°53'·30N 3°10'·44W

Insert 1·0m in 48°52'·58N 3°08'·55W ILNW 325/23

Replace depth: 1·9m with drying rock sym in

48°52'·50N 3°08'·18W ILNW 325/23

Move R buoy Q.R Basse Crublent to: 48° 54'·21N

3° 11'·24W. NM941/2024

Delete House in (a) 48° 51'·00N. 3° 07'·11W.

Delete leading line, pecked line, joining: (a) above
48° 51'·55N 3° 07'·88W RE FN 41/46/23

p348 **LANNION RIVER**, Plan

Locquémeau. **Amend** Range W sector to 8, all other
characteristics unchanged, in 48°43'·28 N 3°34'·11 W.
BA Lights Wk8/24

p352 **ILE DE BATZ** Plan

Delete BYB E card Bn in 48°43'·75N 3°59'·42W
ILNW 34/23)

Replace BY N cardinal Bn Tr with W Bn Tr in

48°44'·10N 3°59'·70W ILNW 24/24

France, West Coast

p366 **CONCARNEAU**, Text

Facilities Insert Fuel RE

p378 **LES SABLES D'OLONNE**, Plan

Insert sectors at light, Iso.4s33m16M in: 46° 29'·58N.,
1° 46'·23W as follows W 25°- 40° (15°) NM4008/23

Northwest Spain

p388 **HONDARRIBIA AND HENAYE**, Plan

Insert Y special spar buoy in 43°22'·02N 1°47'·05W
ILNW 43/23

p391 **PUERODE BILBAO**, Plan

Amend Lt: Fl(2)G.8s1M to Oc(2)G.7s1M in 43°21'·80N
3°04'·65W

Amend Lt: Fl(3)G.10s3M to Fl(4)G.12s3M in
43°20'·79N 3°01'·91W

Amend Lt: Fl(4)G.12s to Fl.G.4s in 43°20'·59N
3°01'·93W

Amend Lt: Fl(3)G.10s to Oc(2)G.7s in 43°19'·81N
3°01'·78W

Amend Lt: Fl(2+1)G.10s to Fl(4)Y.12s in 43°19'·93N
3°01'·60W. ILNW 53/23

p394 **PUERTO DE RIBADESELLA**

The depth to the NW of the marina is no longer maintained. **Delete** lgd 1.5m centred on 43°27'·89N 5°03'·75W ILNW 19/23

p400 **A CORUÑA/LA CORUÑA**, Text

Marina Carunna: **Amend** tel to 881 920 482. RE

p407 **RÍA DE VIGO**, Plan

Replace YBY W card Lt buoy VQ(9)10s with BY N card pillar Lt buoy Q in 42°09'·29N 8° 53'·21W

ILNW 20/24

Text Col3 Line 2: **Replace** Las Serralleiras W card with Las Serralleiras N card. Ed

Portugal, Southwest Spain, and Gibraltar

p 413 **LISBOA APPROACHES**, Plan

Move G pillar Lt buoy No 5 Fl.G.4s from 38°40'·43N 9°17'·66W to 38°40'·47N 9°17'·77W ILNW 339/23

p415 **SINES Marina**

The marina remains closed until all repairs are completed. There is no confirmed date for reopening, last update 14th November 2023. The adjacent anchorage is still available with landing on the beach. For current position contact

portoderecreio@portodesines.pt RE

p416 **PORTIMAO** Plan

Delete anchorage sym in 37°07'·75N 8°31'·63W ILNW 170/23

p417 **VILAMOURA**, Plan

Amend range of Lt Fl.5s17m19M to 12M in 37°04'·47N 8°07'·38W ILNW 26/23

p418 **VILA LA REAL DE SANTO ANTONIO**, Plan

Insert Lt: Fl(2)R.5s in 37°12'·10N 7°24'·88W Fl(2)G.5s in 37°12'·14N 7°24'·88W. ILNW 18/24

TIDE TABLE BOOKLET

p1 Move ((Devenport) currently following Portsmouth so that it follows Plymouth. RE 2/24

p96 **BREST - TIDAL COEFFICIENTS**

Amend 2023 to 2024 ILNW

-----+++++++-----

-----+++++++-----