

Imray Correction Notice

17 November 2011

Chart 2200+9 WGS 84

Edition Dec 2007

Date of printing Dec 2007

The following corrections should be noted:

1 Beaulieu River, Exbury Point westwards (Plan H)

Insert minor Lts 2F.G(vert) in:

50°47'·17N 1°24'·65W

50°47'·32N 1°24'·54W

Amend lgd *Mooring Piles* to *Mooring Pontoon* between these Lts. (ILNW 452/08)

2 Approaches to Newtown River

Substitute W card pillar Lt buoy Q(9)15s for R spher Lt buoy Fl.R.4s in 50°43'·76N 1°24'·91W (ILNW 460/09)

3 Bembridge Harbour (Inset)

Delete G con buoy **11A** in 50°41'·66N 1°05'·74W (ILNW 488/09)

4 Beaulieu River entrance (Plan H)

Delete Lt sector at **Lepe NB** Fl.R.5s3M Lt bn in 50°46'·86N 1°21'·76W (ILNW 1/10)

5 Keyhaven (Plan J)

Substitute drying height -2m for depth 0·3m in 50°42'·85N 1°33'·29W and extend drying area N to enclose. (ILNW 203/10)

6 Newtown River (Plan B)

Substitute iso danger bn for RGR bn in 50°43'·37N 1°24'·53W (ILNW 246/10)

7 Keyhaven (Plan J)

Following a recent survey, the entrance markers and leading posts at Keyhaven have been moved. Delete the existing 2 B bns, R spher buoy and G con buoy.

Insert:

B bn in 50°42'·99N 1°33'·38W

B bn in 50°43'·00N 1°33'·39W

R spher buoy in 50°42'·89N 1°33'·20W

G con buoy in 50°42'·90N 1°33'·17W

Add ldg line from 2 bns, extending in direction 124° (between the 2 buoys). Add lgd 304° at seaward end.

In addition, new starboard hand markers have been established in the river. Full details of these, alongside revised depths, will be included on the next edition of this chart. (ILNW 462/10)

8 Approaches to Cowes (Plan C)

Delete Y mooring buoy in 50°46'·10N 1°17'·09W (ILNW 419/11)