

# Imray Correction Notice

08 December 2011

## Chart M14 WGS 84

*Edition Jul 2010*

*Date of printing Jul 2010*

The following corrections should be noted:

### 1 **Gruissan southwards**

Insert dangerous wk sym in 43°04'·28N 3°06'·48E (ILNW 302/10)

### 2 **Approaches to Golfe de Fos**

Insert *A/S* at **Omega** Lt buoy in 43°11'·93N 5°01'·80E (ILNW 381/10)

### 3 **Approaches to Barcelona**

Add *A/S* to safe water pillar Lt buoy Mo(A)10s3M Racon(B) in 41°16'·91N 2°10'·88E (ILNW 426/10)

### 4 **Blanes southeastwards**

Move *ODAS* Lt buoy FI(5)Y.20s in 41°36'·48N 2°52'·02E to 41°39'·75N 2°54'·57E (ILNW 431/10)

### 5 **Apps to Barcelona**

Insert Y *ODAS* Lt buoy FI(5)Y.20s in 41°16'·65N 2°08'·28E and delete Y spher Lt buoy FI(5)Y.20s close by (ILNW 85/11)

### 6 **Approaches to Sète**

Insert *A/S* at safe water Lt buoy in 43°18'·7N 3°50'·1E (ILNW 222/11)

### 7 **Golfe d'Aigues Mortes, Palavas-les-Flots**

Amend Lt FI.R&FI(2)G to FI(2)R&FI(3)G in 43°31'·5N 3°56'·2E (ILNW 308/11)

### 8 **Barcelona eastwards (Plans A & B)**

Insert E card pillar Lt buoy VQ(3)5s in 41°22'·19N 2°11'·65E and delete E card spindle Lt buoy Q(3)10s close by. (ILNW 361/11)

### 9 **Canet-Plage eastwards**

Delete Y pillar Lt buoy FI(5)Y.20s in 42°42'·6N 3°04'·8E (ILNW 396/11)

### 10 **Approaches to Golfe du Lion**

Delete Y *ODAS* Lt buoy FI(5)Y.20s in 42°06'·4N 4°41'·8E [new position off chart] (ILNW 441/11)