

Imray Correction Notice ICY33-3

21 January 2021

Chart Y33 WGS 84

Edition 2016

Versions available:

New Edition (corrected to June 2016)

Update (corrected to April 2019)

Update (corrected to April 2020)

NOTES

Below is a complete list of corrections issued since the 2016 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.

Any further corrections will be applicable from that point onwards.

1 **The Winner N**

Move G con. Lt buoy **Mid Winner** from 50°47'·38N 0°55'·69W to 50°47'·40N 0°55'·72W.

Extend 0m contour N to include 50°47'·39N 0°55'·71W. (ILNW 400/16)

2 **Chichester Harbour**

Replace G con buoy **N Pilsey** with G con Lt buoy **N Pilsey** Fl(2)G.5s in 50°47'·74N 0°56'·33W (ILNW 429/17)

3 **Chichester Harbour**

Replace BYB E card Bn with Y special Bn in 50°47'·30N 0°56'·28W. Tide gauge on the Bn is unchanged. (ILNW 680/17)

4 **Cobnor Point N**

Replace label Bosham SC with label Cobnor Activities Centre Trust centred on 50°49'·04N 0°52'·65W (ILNW 340/18)

5 **Langstone Harbour, Broom Channel**

Amend Lt desc. at R can Lt buoy Fl(2)R.10s to Fl.R.2s in 50°49'·32N 1°02'·30W (ILNW 453/19)

6 **Approaches to Chichester Harbour**

Insert dangerous Wk sym in 50°45'·41N 0°56'·68W (ILNW 522/19)

7 **Chichester Harbour**

Insert:

Obstr, drying height -1·4m in 50°47'·76N 0°56'·14W

Obstr, drying height -1·6m in 50°47'·11N 0°55'·50W (ILNW 545/19)

8 **Langstone Harbour, Broom Channel**

Insert depth 1·9m in 50°48'·77N 1°01'·84W. Delete depth 2·6m close SE

Insert drying height -0·2m in 50°48'·69N 1°01'·75W & extend 0m contour S to enclose (ILNW 646/19)

9 **Chichester Harbour, East Head N**

Move G con buoy from 50°47'·42N 0°54'·70W to 50°47'·43N 0°54'·65W (ILNW 638/20)

10 **Langstone Harbour**

Move R can Lt buoy:

VQ.R from 50°48'·75N 1°01'·84W to 50°48'·69N 1°01'·82W

Fl.R.4s from 50°49'·10N 1°02'·12W to 50°48'·99N 1°02'·07W

Delete R port hand bn in 50°48'·21N 1°01'·86W

Insert G con buoy in:

50°49'·80N 0°59'·56W

50°49'·18N 1°02'·15W

50°49'·06N 1°02'·07W

50°48'·03N 1°00'·98W (ILNW 28/21)

11 Approaches to Southsea Marina (Plan A)

Changes have been made to the lights and beacons marking the approach to Southsea Marina. Full details will be included in the forthcoming new edition of this chart (ILNW 29/21)