

# Imray Correction Notice ICY9-3

4 February 2021

## Chart **Y9** WGS 84

*Edition 2018*

*Versions available:*

*New Edition (corrected to March 2018)*

*Update (corrected to March 2019)*

*Update (corrected to March 2020)*

*Update (corrected to February 2021)*

### NOTES

*Below is a complete list of corrections issued since the 2018 edition of this chart was published.*

*Each correction is issued with an ILNW reference number and year.*

*Corrections are listed chronologically in ascending order.*

*For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.*

*Any further corrections will be applicable from that point onwards.*

#### 1 **Race Bank**

Delete Y special pillar Lt buoy Fl.Y.5s in 53°12'·95N 0°53'·43E (ILNW 239/18)

#### 2 **The Wash**

Replace G con Lt buoy **No1** Fl.G.3s with Y con Lt buoy **No1** Fl.Y.3s in 52°56'·00N 0°21'·50E (ILNW 332/18)

#### 3 **King's Lynn (Plan B)**

Insert G starboard Bn in 52°45'·27N 0°23'·38E (ILNW 345/18)

#### 4 **The Wash**

Insert BRB isolated danger Lt buoy:

**Z9** Fl(2)6s in 52°59'·73N 0°22'·75E

**Z6** Fl(2)6s in 52°57'·52N 0°19'·17E (ILNW 665/18)

#### 5 **King's Lynn (Plan B)**

Delete R port Lt Bn Q.R in 52°45'·32N 0°23'·48E (ILNW 1/19)

#### 6 **Old Lynn Road W**

Insert YBY W cardinal pillar Lt buoy Q(9)15s (2 buoys) in 52°51'·78N 0°14'·73E (ILNW 21/19)

#### 7 **Holbeach Firing Practice Area** (correction amended see ILNW 467/19 & 643/19)

Insert:

Y con buoy **DZ No 10** in 52°51'·65N 0°12'·93E

Y special pillar buoy **DZ No 11** in 52°50'·88N 0°12'·63E. Delete Y con Lt buoy **RAF No6** Fl.Y.3s close NW

Amend name of Bn **RAF No1** to **DZ No 1** in 52°53'·75N 0°06'·33E

Replace:

Y Bn **RAF No2** with Y con buoy **DZ No 2** in 52°54'·42N 0°07'·48E

Y Bn **RAF No2A** with Y con buoy **DZ No 3** in 52°54'·75N 0°08'·72E

Y Lt Bn **RAF No3** Fl.Y.5s with Y con buoy **DZ No 4** in 52°55'·00N 0°09'·77E

Y Lt Bn **RAF No4** Fl.Y.10s with Y pillar buoy **DZ No 5** in 52°55'·10N 0°11'·47E

Delete Y Lt Bn **RAF No5** Fl(2)Y.5s in 52°51'·39N 0°13'·00E

(ILNW 176/19)

#### 8 **Holbeach Firing Practice Area** (correction amended see ILNW 643/19)

Amend name of Y con buoy:

**RAF No1** to **DZ No 6** in 52°54'·37N 0°12'·89E

**RAF No2** to **DZ No 7** in 52°53'·74N 0°13'·32E

Amend name of Y con Lt buoy:

**RAF No3** to **DZ No 8** in 52°52'·98N 0°13'·29E (ILNW 271/19)

**9 Approaches to River Nene**

Delete YBY W card pillar Lt buoy Q(9)14s (2 buoys) in 52°51'·78N 0°14'·72E (ILNW 407/19)

**10 Holbeach Firing Practice Area** (*correction amended see ILNW 643/19*)

Insert Y con Lt buoy:

**DZ No 11** Fl.Y.3s in 52°50'·93N 0°12'·52E. Delete Y special pillar buoy **DZ No 11** close SE.

**DZ No 10** Fl(2)Y.5s in 52°51'·39N 0°13'·00E

Amend name of BYB E cardinal Lt Bn **RAF No4** to **DZ No 9** in 52°52'·54N 0°13'·10E

Delete Y con buoy **DZ No 10** in 52°51'·65N 0°12'·93E (ILNW 467/19)

**11 Black Buoy Sand**

Replace Y special con buoy with Y special spher. Lt buoy Q.Y in:

52°55'·99N 0°06'·63E

52°56'·04N 0°06'·12E (ILNW 623/19)

**12 Holbeach Firing Practice Area**

Insert Y con buoy:

**DZ No 8** in 52°53'·02N 0°13'·31E. Delete Y con Lt buoy **DZ No 8** Fl.Y.5s close SW

**DZ No 10** in 52°51'·65N 0°12'·95E

**DZ No 11** in 52°50'·89N 0°12'·63E. Delete Y con Lt buoy **DZ No 11** Fl.Y.3s close NW

Delete Y con Lt buoy **DZ No 10** Fl(2)Y.5s in 52°51'·39N 0°13'·00E (ILNW 643/19)

**13 Old Lynn Channel**

Insert Y special pillar Lt buoy **Z2** Fl(4)Y.10s in 52°54'·05N 0°16'·11E (ILNW 2/20)

**14 Approaches to Boston**

Amend Lt desc. at G con buoy **No13N** Fl.G.6s to Fl.G.3s in 52°56'·48N 0°06'·71E (ILNW 24/20)

**15 The Wash**

Delete:

BY N cardinal pillar Lt buoy **Seal Sand Q** in 52°56'·00N 0°20'·00E

YBY W cardinal pillar Lt buoy **Sunk Q(9)15s** in 52°56'·29N 0°23'·40E (ILNW 36/20)

**16 The Well**

Insert BRB isolated danger Lt buoy Fl(2)10s in 53°01'·53N 0°25'·66E. (ILNW 208/20)

**17 Wells-next-the-Sea (Main chart & Plan D)**

Move YBY W card Lt buoy Q(9)15s from 52°59'·73N 0°50'·52E to 52°59'·68N 0°50'·24E (ILNW 326/20)

**18 Old Lynn Channel**

Delete Y special pillar buoy **Z2** Fl(4)Y.10s in 52°54'·05N 0°16'·11E (ILNW 338/20)

**19 King's Lynn (Plan B)**

Insert minor R Lt 2F.R(vert) in 52°45'·10N 0°23'·58E. This marks the end of the jetty extension (ILNW 567/20)

**20 Outer Westmark Knock**

Move BYB E card Lt buoy **East Knock** from 52°52'·06N 0°14'·66E to 52°52'·14N 0°14'·69E (ILNW 631/20)