

# Imray Correction Notice

ICG23-2

23 May 2024

## Chart G23

WGS 84

Edition 2018

### Versions available:

*New Edition (corrected to August 2018)*

*Update (corrected to August 2019)*

*Update (corrected to January 2021)*

*Update (corrected to January 2022)*

*Update (corrected to January 2023)*

*Update (corrected to January 2024)*

### NOTES

*Below is a complete list of corrections issued since the 2018 edition of this chart was published.*

*Each correction is issued with an ILNW reference number and year.*

*Corrections are listed chronologically in ascending order.*

*For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.*

*Any further corrections will be applicable from that point onwards.*

#### 1 **Aydinli Limani**

Insert Igd *Works in Progress* (2018) centred on 40°50'·8N 29°15'·6E (ILNW 620/18)

#### 2 **Tuzla Körfezi**

Amend range of Lt Hayirsizada Fl.3s10M to 7M in 40°47'·4N 29°15'·8E (ILNW 672/18)

#### 3 **Silivri**

Amend Lt Fl.G&R.5s5M to Fl.R.5s5M in 41°04'·30N 28°14'·34E. AIS remains unchanged. (ILNW 238/19)

#### 4 **Silivri SW**

Insert Y special pillar Lt buoy Fl.Y.3s in:

41°02'·42N 28°09'·93E

41°02'·39N 28°12'·78E (ILNW 239/19)

#### 5 **Yalova**

Insert Lt Fl(4)Y.10s5M in:

40°39'·63N 29°16'·22E

40°39'·70N 29°16'·79E

Amend range of Lt Fl.G&R.3s8M to 5M in 40°39'·65N 29°14'·76E. AIS remains unchanged. (ILNW 242/19)

#### 6 **Princes Islands, Kinaliada (Plan C)**

Delete Y special con Lt buoy Fl.Y in 40°54'·98N 29°02'·58E (ILNW 306/19)

#### 7 **West Istanbul Marina SW** (*correction superseded see ILNW 526/19*)

Insert drying wreck in 40°57'·43N 28°39'·27E (ILNW 421/19)

#### 8 **Approaches to Pendik (Plan D)**

Amend Lt desc. at Y special can Lt buoy Fl.Y.5s to Fl(4)Y.20s in 40°51'·38N 29°14'·18E (ILNW 455/19)

#### 9 **West Istanbul Marina SW**

Delete drying wreck in 40°57'·43N 28°39'·27E (ILNW 526/19)

#### 10 **Yalova**

Insert Lt Fl(2)G.4s5M in 40°39'·71N 29°16'·44E (ILNW 591/19)

#### 11 **Bakirköy E**

Delete drying wreck sym. in 40°59'·03N 28°55'·30E (ILNW 632/19)

**12 Approaches to Pendik (Plan D)**

Delete BRB isolated danger pillar Lt buoy FI(2)10s4M in 40°51'·15N 29°15'·61E (ILNW 700/19)

**13 Marmara Denizi**

Amend Lt FI.R&G.5s7M to FI.R&G.3s2M in 40°54'·16N 27°28'·14E

Delete BRB isolated danger pillar Lt buoy FI(2)10s plus racon sym. & assoc. lgd A/S in 40°32'·70N 27°16'·17E (ILNW 30/20)

**14 Approaches to Pendik (Plan D)**

Insert mooring buoy sym. in 40°51'·88N 29°14'·79E

Delete Y special can buoy in 40°51'·64N 29°14'·06E (ILNW 97/20)

**15 Istanbul Bogazi (Plan B)**

Delete Y special con Lt buoy FI&FI.Y.3s in:

41°02'·52N 29°02'·13E.

41°00'·20N 29°00'·10E. (ILNW 193/20)

**16 Tuzla**

Amend Lt from FI.R.5s5M to FI(2)6s10M in 40°48'·71N 29°17'·85E (ILNW 199/20)

**17 Karaburun N supersedes (in part) ILNW 30/20**

Insert BRB isolated danger pillar Lt buoy FI(2)10s plus racon sym. & assoc. lgd A/S in 40°32'·70N 27°16'·17E (ILNW 224/20)

**18 Silivri SW**

Insert lit platform symbol in:

41°02'·68N 28°10'·87E

41°02'·02N 28°11'·64E

Delete Y spher lt buoy FI(5)Y.20s close N (ILNW 323/20)

**19 Karabiga, Marmara Denizi**

Amend range of Lt from:

FI.5s8M to FI.5s10M in 40°24'·66N 27°20'·04E

FI.Y.7M to FI.Y.3M in 40°24'·20N 27°18'·27E

(ILNW 375/20)

**20 Marmara Adasi (Main chart & Plan A)**

Amend range of Lt from:

FI.G.3s10M to FI.G.3s5M in 40°39'·53N 27°39'·78E

FI(3)15s12M to FI(3)15s7M in 40°34'·61N 27°34'·44E (ILNW 486/20)

**21 Yildiz Kayaligi (Main chart & Plan C)**

Replace YBY W cardinal Lt bn VQ(9)10s10M with BRB isolated danger Lt bn FI(2)5s10M (FI(2)5s10m10M Plan C) in 40°56'·23N 29°05'·34E. AIS remains unchanged (ILNW 606/20)

**22 Yassiada**

Insert Lt FI(2)8s10M in 40°51'·95N 28°59'·46E (ILNW 25/21)

**23 Izmit**

Delete lgd Works in progress (2017) centred on 40°45'·50N 29°50'·90E (ILNW 168/21)

**24 Princes Islands (Plan C)**

Insert fish haven symbol centred on:

40°55'·10N 29°02'·68E

40°52'·45N 29°04'·24E (ILNW 200/21)

**25 Fener Br. (Plan B)**

The entry prohibited area centred on 40°58'·00N 29°01'·50E has been enlarged to the now superseded extents of the no anchoring and fishing area around its perimeter. (ILNW 209/21)

**26 Tuzla**

Amend Lt from FI(2)6s10M to FI.R.5s5M in 40°48'·71N 29°17'·85E. The AIS at this light remains unchanged (ILNW 223/21)

**27 Kinaliada N (Plan C)**

Insert Y superbuoy with special purpose topmark FI(5)Y.20s ODAS with assoc. Racon(U) in 40°55'·10N 29°02'·31E (ILNW 509/21)

**28 Istanbul, Middle Harbour (Plan B)** *(Correction amended see ILNW 347/23)*

Insert YB S cardinal pillar Lt buoy Q(6)+LFI.15s in:

41°01'·87N 28°59'·59E

41°02'·03N 28°59'·81E (ILNW 515/21)

**29 Bandırma Korfezi, Mola Banki**

Insert YB S card Lt bn Q(6)+LFI.15s in 40°26'·32N 28°06'·11E. Delete YB S card Lt buoy close S (ILNW 546/21)

**30 Approaches to Pendik (Plan D)**

Delete drying Wk sym. in 40°51'·30N 29°15'·60E (ILNW 622/21)

**31 Approaches to Pendik (Plan D)**

Delete mooring buoy in 40°51'·89N 29°14'·79E (ILNW 623/21)

**32 Narlıköy (Plan A)**

Insert Lt FI.R&G.3s3M in 40°28'·32N 27°41'·30E (ILNW 165/22)

**33 Beşiktaş S (Plan B)**

Delete BRB isolated danger pillar Lt buoy FI(2)12s in 41°02'·31N 29°00'·30E (ILNW 217/22)

**34 Istanbul City Port (Main chart & Plan D)**

Amend Lt FI(3)10s5m7M to FI.R.3s9m3M in 40°52'·08N 29°14'·38E (ILNW 495/22)

**35 Approaches to Pendik (Plan D)**

Delete drying Wk sym. in:

40°52'·35N 29°14'·66E

40°52'·25N 29°14'·83E (ILNW 501/22)

**36 Approaches to Pendik (Plan D)**

Delete Y special can Lt buoy FI.Y.4s in 40°52'·23N 29°14'·48E (ILNW 502/22)

**37 Karabiga NE**

Amend range of Lt FI.Y.3s5M to 3M in 40°25'·42N 27°19'·92E (ILNW 76/23)

**38 Maltepe (Main Chart & Plan C)**

Delete dangerous wk symbol in 40°55'·05N 29°06'·78E (ILNW 271/23)

**39 Istanbul (Plan B)**

Insert Lt FI.Y in 40°58'·73N 29°01'·50E (ILNW 300/23)

**40 Büyükkada W (Plan C)**

Insert dangerous wk sym in 40°52'·18N 29°06'·73E (ILNW 344/23)

**41 Istanbul, Middle Harbour (Plan B)**

Delete YB S cardinal pillar Lt buoy Q(6)+LFI.15s in:

41°01'·87N 28°59'·59E

41°02'·03N 28°59'·81E (ILNW 347/23)

**42 Marmara Adasi S (Main chart & Plan A)**

Insert underwater rock sym enclosed by a dangerline in 40°34'·73N 27°35'·89E (ILNW 168/24)

**43 Buyukkumla**

Amend range of Lt FI(4)Y.15s5M to 3M in 40°27'·95N 29°06'·04E (ILNW 169/24)

**44 Marmara (Main chart & Plan A)**

Amend range of Lt to FI.R&G.3s5M in 40°35'·02N 27°33'·65E (ILNW 205/24)