Imray Correction Notice ICM8-2

23 May 2024

Chart M8 wgs 84

Edition 2020

Versions available:

New Edition (corrected to March 2020) Update (corrected to April 2022) Update (corrected to April 2023) Update (corrected to March 2024)

NOTES

Below is a complete list of corrections issued since the 2020 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction. Any further corrections will be applicable from that point onwards.

1 Capo Caccia W

Replace Y special purpose spher Lt buoy FI(5)Y.20s with Y superbuoy *ODAS* FI(5)Y.20s in 40°32′·90N 8°06′·46E (ILNW 562/21)

2 Secca di Tre Monti (Plan A)

Move BRB Isolated danger bn FI(2)8s5M from 41°09'·40N 9°27'·75E to 41°09'·35N 9°27'·90E (ILNW 321/22)

3 Bonifacio Strait

Insert Y special purpose pillar Lt buoy ODAS FI(4)Y.15s (2 buoys) 41°19'.50N 8°52'.40E (ILNW 157/23)

4 Palau (Plan A)

Replace YBY W cardinal Lt Bn & radar reflector VQ(9)10s5M with YBY W cardinal spar Lt buoy VQ(9)10s in 41°10'·96N 9° 23'·26E (ILNW 236/23)

5 Add chart note:

Chart accuracy (Plan D)

Due to the nature of the source information, some detail may not be positioned accurately, and uncharted dangers may exist. Exercise caution when navigating along the coast or in the vicinity of dangers, even when using a satellite positioning system. (ILNW 282/23)

6 Isola delle Bisce E (Plan A)

Insert depth 2.6m in 41°09'.98N 9°31'.64E. Extend 5m contour E to enclose (ILNW 209/24)