

Imray Correction Notice ICM27-2

23 May 2024

Chart M27 WGS 84

Edition 2018

Versions available:

New Edition (corrected to July 2018)

Update (corrected to July 2019)

Update (corrected to April 2021)

Update (corrected to April 2022)

Update (corrected to March 2024)

NOTES

Below is a complete list of corrections issued since the 2018 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.

Any further corrections will be applicable from that point onwards.

1 **Boka Kotorska (Plan D)**

Insert Lt Fl.R.3s7m4M in 42°25'·92N 18°36'·26E (ILNW 26/19)

2 **Tivat (Plan D)**

Move Lt Fl.3s7M in 42°25'·89N 18°41'·44E to 42°25'·87N 18°41'·27E (ILNW 498/19)

3 **Tivat (Plan E)** (*correction amended see ILNW 158/20*)

Insert Lt Fl.R.4s4m5M in 42°26'·02N 18°41'·46E

Amend Lt:

Fl.R.4s5M to Fl.R.4s4m5M in 42°26'·00N 18°41'·33E

Fl.G.4s5M to Fl.G.4s4m3M in 42°26'·03N 18°41'·23E

Fl.3s7M to Fl.3s9m7M in 42°25'·87N 18°41'·27E

Fl.R.4s5M to Fl.R.4s4m3M in 42°25'·79N 18°41'·29E

Fl(2)6s6m3M to Fl(2)R.6s6m3M in 42°25'·82N 18°41'·71E

Delete Lt Fl.W.R in 42°25'·89N 18°41'·44E (ILNW 498/19)

4 **Hr. Ruda (Plan B)**

Insert BY N cardinal Lt Bn VQ.6m2M in 42°42'·71N 17°55'·70E (ILNW 6/20)

5 **Boka Kotorska (Plan D)**

Insert dangerous wreck sym. in 42°25'·99N 18°34'·08E

Delete Lt Fl(2)R.6s5m2M in 42°27'·15N 18°33'·32E (ILNW 156/20)

6 **Budva (Plan F)**

Delete Lt Fl.R.3s6m3M in 42°16'·76N 18°50'·36E (ILNW 157/20)

7 **Tivat (Plan E)**

Delete Lt Fl.R.4s4m5M in 42°26'·02N 18°41'·46E (ILNW 158/20)

8 **Tivatski Zaljev (Main chart & Plan D)**

Insert dangerous wk sym in 42°25'·02N 18°41'·80E (Plan D)

Amend Lt Fl(2)WR.5s8m6/4M to Fl.WR.5s8m6/4M in 42°24'·98N 18°40'·69E (Main chart & Plan D) (ILNW 635/20)

9 **Bar (Plan G)**

Delete *Obstn* with a depth of 6.2m in 42°06'·14N 19°05'·05E (ILNW 117/21)

10 **Tivatski Zaliv (Main chart & Plan D)**

Amend Pl. Tunja Lt from Fl.WR.5s8m6/4M to Fl(2)WR.5s8m6/4M in 42°24'·98N 18°40'·69E (ILNW 483/21)

11 Luštica Peninsula N (Plan D)

Insert restricted area, entry prohibited joining:

42°25'·56N 18°36'·10E

42°25'·58N 18°37'·50E

42°25'·14N 18°37'·50E (ILNW 514/21)

12 Rt Oštra (Main chart & Plan D)

Amend Lt to Fl(2)10s73m15M in 42°23'·60N 18°31'·86E. Add assoc racon sym and lgd AIS (ILNW 170/22)

13 Approaches to Boka Kotorska

Insert Y special purpose pillar Lt buoy *ODAS* Fl.Y.3s5M with *AIS* in 42°23'·70N 18°21'·50E (ILNW 534/22)

14 Otok Jakljan (Plan B)

Amend vertical clearance height from 49m to 46m in 42°44'·21N 17°50'·20E (ILNW 383/23)

15 Donji Kostanjica (Plan D)

Replace Lt F.R.4m3M with F.G in 42°29'·22N 18°39'·94E (ILNW 136/24)

16 Goli Rat, Otok Mljet

Delete circular entry prohibited area centred on 42°47'·08N 17°19'·12E (ILNW 203/24)