

Imray Correction Notice

ICC33B-3

28 October 2024

Chart C33B

WGS 84

Edition 2022

Versions available:

New Edition (corrected to October 2022)

Update (corrected to April 2023)

Update (corrected to February 2024)

NOTES

Below is a complete list of corrections issued since the 2022 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.

Any further corrections will be applicable from that point onwards.

1 Grand Léjon NE

Delete Y special pillar Lt buoy Fl(5)Y.20s in 48°45'·76N 2°36'·52W (ILNW 84/23)

2 St Malo Approaches (Main chart & Plan F)

Insert rock which covers/uncovers sym. in 48°39'·48N 2°01'·71W (Main chart & Plan F) add assoc. drying height -0·2m (Plan F)

Replace depth 4·8m with depth 3·3m in 48°40'·40N 2°02'·18W (Plan F) (ILNW 204/23)

3 Jersey S, Noirmont Pt W (Main chart & Plan I)

Insert limit of restricted area, no fishing, joining:

49°10'·15N 2°10'·97W (Main chart)

49°10'·05N 2°10'·55W (Plan I W edge)

49°10'·01N 2°10'·37W (Main chart & Plan I) (ILNW 232/23)

4 St Malo Approaches (Plan F)

Delete restricted area, no fishing, and assoc. Y special con buoys in:

48°40'·74N 2°03'·18W

48°40'·74N 2°02'·78W

48°40'·44N 2°02'·78W

48°40'·44N 2°03'·18W (ILNW 235/23)

5 Cap Fréhel W

Replace depth:

6·2m with 1·4m in 48°41'·42N 2°24'·07W

3·9m with 2·9m in 48°41'·32N 2°23'·52W

4·6m with 1·1m in 48°40'·80N 2°20'·57W (ILNW 324/23)

6 Chenal de la Grande Porte (Plan F)

Move R pillar Lt buoy **No 2** Fl.R.2·5s from 48°40'·23N 2°07'·48W to 48°40'·24N 2°07'·35W

Delete:

R pillar Lt buoy **No 4** Bell in 48°40'·24N 2°07'·20W

R can buoy **No 6** in 48°40'·26N 2°06'·13W (ILNW 356/23)

7 St Helier Approaches (Plan I)

Insert Y can Lt buoy Fl.Y.3s in:

49°10'·80N 2°07'·95W

49°09'·92N 2°06'·60W (ILNW 44/24)

8 Saint-Malo (Plan F & G)

Replace depth 2·2m with 1·7m in 48°38'·21N 2°02'·15W (ILNW 152/24)

9 Granville (Plan H)

Delete fog signal Horn(2)40s at Lt Fl(2)R.6s5M in 48°49'·89N 1°35'·89W (ILNW 181/24)

10 Rade de Dinard (Plan G)

Insert can mooring buoy sym.:

Dinard CO1 in 48°38'·25N 2°02'·51W

Dinard CO2 in 48°38'·07N 2°02'·36W. Delete can mooring buoy close SE

Dinard CO3 in 48°37'·94N 2°02'·26W. Delete can mooring buoy close SE (ILNW 487/24)

11 Saint-Brieuc Wind Farm

Construction works for the Saint-Brieuc Wind Farm is completed.

Delete N card Lt buoy Q in 48°56'·80N 2°36'·10W

Insert:

Lit platform Mo(U)45m10M in 48°50'·97N 2°31'·97W.

Wind turbine Oc(4)Y.12s5M plus assoc. racon sym. and lgd AIS in 48°55'·39N 2°34'·08W

Wind turbine Oc(4)Y.12s5M plus assoc. racon sym. and lgd AIS in 48°47'·89N 2°30'·36W

Y pillar Lt buoy Fl(5)Y.20s in 48°54'·53N 2°37'·00W

Y pillar Lt buoy Fl(5)Y.20s in 48°47'·75N 2°26'·91W

Replace lgd *Wind Farm under const'n* with lgd Saint-Brieuc Wind Farm centred on 48°51'·91N 2°32'·94W

Full details will be included on the next edition of this chart (ILNW 497/24)