

Imray Correction Notice

ICC31-3

26 February 2025

Chart C31 WGS 84

Edition 2019

Versions available:

New Edition (corrected to July 2019)

Update (corrected to February 2021)

Update (corrected to February 2022)

Update (corrected to February 2023)

Update (corrected to February 2024)

NOTES

Below is a complete list of corrections issued since the 2019 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.

Any further corrections will be applicable from that point onwards.

1 Brighton S

Insert Y spar Lt buoy Fl.Y.6s in 50°47'·41N 0°06'·73W

Amend duration of Lt at Y spar Lt buoy Fl.Y.6s to 5s in 50°47'·68N 0°08'·43W (ILNW 406/19)

2 Ridens de Dieppe NW

Delete Y special pillar Lt buoy ODAS Fl(5)Y.20s & racon sym. plus assoc. lgd A/S in 50°07'·43N 1°00'·85E (ILNW 454/19)

3 Le Havre

Amend Lt:

Fl.R.5s21M to Fl.R.4s8M in 49°29'·19N 0°05'·44E

VQ(3)G.11M to Fl.G.4s8M in 49°29'·06N 0°05'·38E (ILNW 630/19)

4 Le Havre Yacht Harbour (Plan H)

Amend Lt:

Fl.R.5s15m21M to Fl.R.4s15m8M in 49°29'·19N 0°05'·44E

VQ(3)G.2s15m11M to Fl.G.4s15m8M in 49°29'·06N 0°05'·38E (ILNW 630/19)

5 Cap Gris Nez NE

A drying bank has formed in the vicinity of 50°53'·40N 1°36'·70E with a drying height of -1.6m. Insert assoc lgd *Less Water* (ILNW 320/20)

6 Cap d'Antifer (correction amended see ILNW 477/22 & 30/23)

Delete Y spec spar Lt buoy:

H1 in 49°38'·03N 0°00'·09W

H2 in 49°51'·40N 0°14'·21E

C1 in 49°56'·64N 0°17'·05E

C2 in 49°55'·66N 0°30'·04E

C3 in 49°51'·89N 0°14'·28E

Insert Y spec spar Lt buoy:

C1 Fl(5)Or.20s (occas) in 49°56'·69N 0°16'·89E

C2 Fl(5)Or.20s (occas) in 49°55'·58N 0°30'·06E

C3 Fl(5)Or.20s (occas) in 49°51'·34N 0°14'·04E (ILNW 37/21)

7 Fécamp NW (correction amended see ILNW 183/24)

Insert Y special purpose super Lt buoy **FECAMP** ODAS Lidar Fl(5)Y.20s with assoc. racon sym and lgd A/S in 50°00'·0N 0°02'·0W (ILNW 85/21)

8 Baie de Seine

Insert limit of restricted area, joining:

49°22'·73N 0°09'·79W

49°22'·22N 0°09'·69W

49°22'·19N 0°10'·01W

49°22'·71N 0°10'·11W

Add assoc. legend *Measuring Instruments (seasonal)*.

Fishing, dredging, trawling and anchoring are prohibited in this area from March to November. (ILNW 186/21)

9 Cap d'Antifer NE

Replace fish haven sym. with circular dangerline & assoc. legend *Obstns* centred on 49°43'·95N 0°11'·65E (ILNW 187/21)

10 Rye Bay

Insert Y sphere Lt buoy FI(5)Y.20s in 50°51'·08N 0°47'·43E (ILNW 382/21)

11 Banc du Ratier (Plan G)

Insert drying height -2·8m in 49°25'·41N 0°07'·21E

Replace drying height -1·9m with drying height -2·5m in 49°25'·47N 0°08'·45E (ILNW 390/21)

12 Pte d'Ailly W, Raz de St Michel

Replace depth 4.2m with 2.2m in 49°54'·48N 0°51'·92E (ILNW 465/21)

13 Sovereign Harbour (Plan A)

Amend sector at Lt DirFI.WRG.5s4m1M in 50°47'·28N 0°19'·71E to 255°-G-259°-W-262°-R-265° (ILNW 82/22)

14 Dungeness

Amend fog signal at Lt from Horn(3)60s to Horn(1)30s in 50°54'·80N 0°58'·55E (ILNW 196/22)

15 Royal Sovereign Lighthouse

The Royal Sovereign Lighthouse is being decommissioned.

Replace **Southern Head** Royal Sovereign Lt FI.20s28m12M Horn(2)30s with YB S card Lt buoy Q(6)+LFI.15s Racon(T) A/S (4 buoys) in 50°43'·46N 0°26'·09E (ILNW 316/22)

16 Fécamp NW (correction amended see ILNW 538/22)

Insert Y special purpose can Lt buoy ODAS FI(5)Y.20s in:

49°57'·59N 0°17'·83E

49°51'·00N 0°15'·72E (ILNW 330/22)

17 Fécamp NW

Insert restricted area joining:

49°50'·19N 0°08'·25E

49°56'·45N 0°13'·01E

49°58'·31N 0°18'·19E

49°50'·20N 0°15'·11E

Add assoc lgd *Wind Farm under construction* (ILNW 341/22)

18 Embouchure de la Seine (Plan G)

Insert Y special Lt superbuoy ODAS SCENES FI(5)Y.20s (buoyed) in 49°28'·84N 0°01'·93E (ILNW 391/22)

19 Fécamp NW (correction amended see ILNW 7/24)

Move Y spec purpose spar Lt buoy:

C1 from 49°56'·69N 0°16'·89E to 49°54'·85N 0°15'·21E

C3 from 49°51'·34N 0°14'·04E to 49°50'·59N 0°14'·30E (ILNW 477/22)

20 Fécamp NW

Move Y special purpose can Lt buoy ODAS FI(5)Y.20s from 49°51'·00N 0°15'·72E to 49°50'·88N 0°15'·19E (ILNW 538/22)

21 Fécamp N

Insert restricted area limit, no anchoring, no fishing, joining:

50°09'·50N 0°16'·70E

50°09'·22N 0°23'·07E

50°08'·73N 0°23'·00E

50°08'·98N 0°16'·64E

Add assoc. symbols no anchoring & no fishing. (ILNW 29/23)

22 St-Pierre-en-Port N

Delete Y spec purpose spar Lt buoy **C2** FI(5)Or.20s (occas) in 49°55'·58N 0°30'·06E (ILNW 30/23)

23 Le Havre-Antifer

Delete Lt Fl.Vi in:

49°40'·19N 0°07'·45E

49°40'·21N 0°08'·31E (ILNW 31/23)

24 Quemer

Insert Y special spher Lt buoy **ODAS** Fl(5)Y.20s (2 buoys) in 50°15'·00N 1°20'·01E (ILNW 39/23)

25 Fécamp NW

Insert YBY W cardinal pillar Lt buoy **FEC-OUEST** Q(9)15s in 49°57'·86N 0°11'·90E (ILNW 40/23)

26 Sovereign Harbour (Plan A)

Delete G con Lt buoy Fl.G.3s in 50°47'·36N 0°20'·21E (ILNW 72/23)

27 Newhaven

Amend Lt Oc(2)10s17m12M to Iso.4s17m12M in 50°46'·55N 0°03'·51E (ILNW 89/23)

28 Eastbourne E

Delete Y can Lt buoy:

Fl.Y.4s in 50°46'·04N 0°19'·00E

Fl.Y.5s in 50°45'·50N 0°21'·80E

Replace Y special purpose can Lt buoy Fl.Y.5s with Y special purpose pillar Lt buoy Fl(4)Y.10s in 50°45'·50N 0°18'·01E

Insert Y special purpose pillar Lt buoy Fl.Y.20s in 50°47'·50N 0°23'·20E (ILNW 119/23)

29 Le Havre-Antifer

Delete lgd at Lt Fl.Vi in

49°40'·21N 0°08'·20E

49°40'·20N 0°07'·70E (ILNW 179/23)

30 Baie de Seine

Delete Y con Lt buoy **MO2** VQ in 49°27'·49N 0°11'·79W (ILNW 303/23)

31 Fécamp (Main chart & Plan F)

Amend Lt duration from Fl(2)10s15m16M to Fl(2)6s15m12M in 49°45'·94N 0°21'·80E (ILNW 364/23)

32 Approaches to Le Havre (Plan G)

Delete Y spher Lt buoy Fl(5)Y.20s in 49°28'·54N 0°01'·05W (ILNW 365/23)

33 Approaches to Le Havre

Delete Y con Lt buoy VQ:

MO1 in 49°27'·56N 0°09'·27W

MO4 in 49°26'·32N 0°06'·45W

MO5 in 49°22'·01N 0°06'·17W (ILNW 378/23)

34 Fécamp NW

Delete Y special purpose Lt spar buoy:

C1 Fl(5)Or.20s (occas) in 49°54'·85N 0°15'·21E

C3 Fl(5)Or.20s (occas) in 49°50'·59N 0°14'·30E (ILNW 7/24)

35 Pte du Haut-Banc S

Move dangerous Wk symbol, and assoc W cardinal spar buoy **FM**, from 50°20'·40N 1°31'·27E to 50°20'·68N 1°31'·98E

Insert Y special purpose pillar Lt buoy **ODAS** Fl(5)Y.20s in 50°08'·05N 1°03'·90E (ILNW 12/24)

36 Cap Gris Nez NE

Replace depth 0·8m with a drying patch in 50°54'·97N 1°39'·38E

Insert depth:

1·7m enclosed by 2m contour in 50°54'·38N 1°38'·24E. Delete depth 2·6m close E

1·3m enclosed by 2m contour in 50°54'·05N 1°37'·51E. Delete depth 2·8m close E (ILNW 30/24)

37 Fécamp (Plan F)

Insert:

drying height -0.3m enclosed by 0m contour in 49°45'·76N 0°21'·99E

Replace:

Obstr depth 1m with depth 0.6m in 49°45'·91N 0°21'·84E

depth 0.3m with drying height -0.3m in 49°45'·73N 0°21'·97E

depth 1.5m with depth 0.9m in 49°45'·76N 0°22'·26E

depth 1.5m with depth 0.4m in 49°45'·72N 0°22'·39E

Delete drying height -0.3m in 49°45'·71N 0°21'·95E, extend 0m contour to enclose insert drying height 0.3m in 49°45'·73N 0°21'·97E (ILNW 79/24)

38 Le Tréport NW, Ridens de Dieppe

Insert restricted area joining:

50°06'·22N 1°01'·34E

50°07'·67N 1°03'·73E

50°08'·99N 1°01'·78E

50°13'·75N 1°09'·63E

50°10'·15N 1°14'·91E

50°03'·97N 1°04'·64E

Anchoring, fishing and diving are prohibited in this area.

Add assoc lgd *Wind Farm under construction* (ILNW 80/24)

39 Fécamp NW

Delete Y special purpose super Lt buoy **FECAMP ODAS Lidar** Fl(5)Y.20s with assoc. racon sym and lgd A/S in 50°00'·0N 0°02'·0W (ILNW 183/24)

40 Le Colbart (The Ridge)

Insert dangerous wreck sym in 50°50'·74N 1°17'·87E (ILNW 322/24)

41 Fécamp Wind Farm

Insert platform sym in 49°52'·2N 0°16'·2E (ILNW 423/24)

42 Vergoyer W

Insert extraction area limit, pecked line, joining:

50°27'·92N 0°51'·61E

50°27'·22N 0°50'·90E

50°25'·81N 0°43'·83E

50°26'·62N 0°43'·29E

50°26'·93N 0°41'·93E

50°26'·68N 0°39'·61E

50°27'·00N 0°39'·41E

50°28'·35N 0°46'·81E

Add assoc. lgd *Extraction Area* (ILNW 457/24)

43 Beachy Head SW

Insert dangerous wreck sym. with assoc lgd *Historic Wk (see Note)* in 50°41'·69N 0°10'·69E (ILNW 473/24)

44 Fecamp NW

Delete W card pillar Lt buoy **FEC-OUEST** Q(9)15s in 49°57'·86N 0°11'·90E (ILNW 545/24)

45 Dover Strait TSS W

Replace R superbuoy sym **Greenwich** with R light-vessel **Greenwich** in 50°24'·52N 0°00'·10W (racon sym and all lgds remain unchanged) (ILNW 590/24)

46 Approaches to River Seine

Insert wreck:

depth 10m in 49°28'·36N 0°04'·23W

depth 10m in 49°27'·07N 0°01'·48E

depth 9m in 49°26'·94N 0°01'·88E (ILNW 40/25)

47 Cap de la Hève E

Insert depth 7.9m in 49°30'·62N 0°02'·45E and extend 10m contour to enclose. Delete depth 7.9m close E (ILNW 41/25)

48 Port du Havre Antifer Approach Channel

Insert racon sym and lgd AIS at N card Lt buoy **A7** Q in 49°44'·54N 0°06'·70W (ILNW 42/25)

49 Fécamp Wind Farm

Construction work on the Fécamp Wind Farm (centred on 49°53'·91N 0°14'·15E) has now been completed. (ILNW 47/25)